

08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC6/CT122000281/453**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: GBE 6644Cat Workshop m/s ff

of _____

Insured: ABG 9007C

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$36k.

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS 3 0056

Vehicle: IN / OUT

Date: _____ Person Contacted: L7A811130Date / Time Action / Instruction 27/9/12Veh No: GBE 6644C Yr Regn: 22/12/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or mi /Make: Toyota Dyna c.c. 2582Colour: silver A/C: Insured / Std / NI / NASp. Reading: 211503 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFAT354706205712Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: M / S/Rim / STD A/Rim orTyre Size: F: 195-1215R: 155-1212

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or KALDEN

Front

Rear

R/Bal. 5 mm R/Bal. 5-15 mmL/Bal. 5 mm L/Bal. 5-15 mmD.O.A. 8/1/12 D.O.I. 10/1/12

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

015 body

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Report Format :

Lump Sum / I.B.I.: (\$) _____)

Add Fee: ☐ : Site Insp (\$) _____) S + RS \$I☐ : Interview (\$) _____) Photos☐ : Tech. Invs (\$) _____) Others☐ : Weekend (\$) _____)

TOTAL

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

sec 110

Not Adhered
dhr
4/5 @ 2500/- 3 days
10/1/22

VEHICLE No: GBE 6644C

118

NET ITEM

1PC	DROPSIDE GATE O/S	DO/Bent	2261.30	\$2,845.20	✓
1PC	DROPSIDE GATE LOWER MEMBER O/S	R		\$878.50	X
1PC	REAR MUDGUARD FRONT PANEL O/S	Bent	265.50	\$285.00	✓
1PC	DROPSIDE GATE STANDED STEEL O/S	cut	180.00	\$600.00	✓
1PC	DROPSIDE GATE RAILING O/S	SC		\$650.00	X
1PC	REAR WHEEL RIM O/S	SC		\$100.00	X
1PC	REAR TYRE O/S	17	25%	\$200.00	X
				\$5,558.70	

TO CHECK WIRING

TO CONDUCT WHEEL ALIGNMENT

TO SPRAY RUST PROOFING

LABOUR FOR PANEL BEATING & REPLACED PARTS

TO PUTTY & SPRAY PAINTING

17	\$50.00	X
	\$100.00	60
	\$60.00	30
	\$580.00	320
	\$880.00	420
TOTAL	\$7,228.70	

2-3106.8
2870.
2330.1
3140.1
2512

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: