

REPAIR DETAILS**Estimates On Parts**

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	TAILGATE	1,998.30	-30.00	1,398.81
2	1	TAILGATE HINGE RH	54.20	-30.00	37.94
3	1	TAILGATE HINGE LH	54.20	-30.00	37.94
4	1	REAR BUMPER	667.20	-30.00	467.04
5	1	REAR BUMPER SIDE RETAINER RH	18.10	-30.00	12.67
6	1	REAR BUMPER SIDE RETAINER LH	18.10	-30.00	12.67
7	1	TAILLAMP RH	247.30	-30.00	173.11
8	1	TAILLAMP LH	247.30	-30.00	173.11
9	1	TAILGATE INNER BOARD	198.00	-30.00	138.60
10	1	END PANEL	460.80	-30.00	322.56
11	1	TAILGATE LOCK	287.10	-30.00	200.97
12	1	TAILGATE ABSORBER RH	215.90	-30.00	151.13
13	1	TAILGATE ABSORBER LH	215.90	-30.00	151.13

Total Parts (\$\$) 3,277.68

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR NUMBER PLATE	35.00	0.00	35.00
2	1	70KM STICKER	70.00	0.00	70.00
3	1	NV350 EMBLEM	95.00	0.00	95.00
4	1	URVAN EMBLEM	95.00	0.00	95.00
5	1	REAR WINDSCREEN MOULDING	120.00	0.00	120.00
6	10	REAR BUMPER CLIP	30.00	0.00	30.00

Sub Total (\$\$) 445.00

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Remove and Refit Rear Bumper Sensor.	80.00	0.00	80.00
2	1	To Transfer Rear Tailgate.	80.00	0.00	80.00
3	1	To Dismantle and Refit Rear Windscreen Glass.	100.00	0.00	100.00
4	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	750.00	0.00	750.00

Gross Labour Cost (\$\$) 1,010.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	80.00	0.00	80.00
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	100.00	0.00	100.00
3	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	80.00	0.00	80.00
4	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape	800.00	0.00	800.00

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

SUPPLEMENTARY

<u>Qty.</u>	<u>Description Of Parts</u>	<u>Pricing</u>
1	TAILGATE INNER LOCK	\$ 287.10 <i>X repeat</i>
1	REAR END STEP PANEL	\$ 460.80 <i>X repeat</i>
1	END PANEL INNER PANEL	\$ 197.10 <i>DT</i>
1	REAR BUMPER BRACKET	\$ 208.00 <i>Br</i>
1	SPARE TYRE CARRIER	\$ 184.30 <i>Xr</i>
1	TAILGATE LOCK GARNISH	\$ 52.50 <i>Xsuc</i>
		List \$ 1,389.80
		Less 30% \$ 416.94
		Total \$ 972.86

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2697

4377

3500