

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard, #04-01 Suntec Tower Three  
Singapore 038988

**Our File No:** CS4/EGI22000288/UQY3E2

**Date:** 02/03/2022

### REFERENCE

Insured/Claimant: LIM JIE MING Policy No: DMPG21010255  
Date of Loss: 07/01/2022 Nature of Claim: OD Claim No: CDMPG22000042

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLV9795Y**  
Make & Model: HONDA FIT, 1.3 L (A) Engine No: L13A4076270  
Reg. Date: 18/02/2009 (Man. Year: 2008) Chassis No: GE61067368  
Colour: Blue Odometer: 0 km  
Engine Capacity: 1339 cc  
Market Value/New Car Price: S\$14,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15  
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm  
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 10/01/2022  
Date Inspected: 10/01/2022 Inspected At: Jin Auto Services Pte Ltd (Defu)  
Blk 14 Defu Lane 10, #01-410/412  
Singapore 539195  
Estimated Period of Repair: 0.0 days

**Adjuster:** MARCUS CHUA

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**TOTAL LOSS ASPECT**

Market Value :	\$14,000.00
OMV :	\$13,940.00
PARF Rebate (1) :	\$ 0.00
Quota Premium Paid :	\$12,864.00
COE Rebate (2) :	\$ 5,411.00
Total Rebate (1) + (2) = :	\$ 5,411.00

The total amount incurred will be Market Value \$14,000.00 minus Total Rebate \$5,411.00 = \$8,589.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 02 Mar 2022)
<b>Parts:</b> 144	HONDA FIT 1.3 L (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLV9795Y)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**