



Your Ref : CDMPG22000042

Date: 02nd Mar 2022

Our Ref : CS4/EGI22000288/Uqy3e2

M/s Ergo Insurance Pte Ltd

8 Temasek Boulevard, #04-01

Suntec Tower Three

Singapore 038988

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SLV 9795Y
ACCIDENT ON 07/01/2022**

Instruction was received to inspect the vehicle Reg. No. SLV 9795Y. The inspection was conducted on 10/01/2022 at the premises of M/s Jin Auto Services Pte Ltd, Blk 14 Defu Lane 10 #01-410/412, Singapore 539195.

The following vehicle information was recorded:

Registration Number	: SLV 9795Y
Make/Model	: Honda Fit 1.3L A
Year of Registration	: 2009
Body Colour	: Blue
Chassis Number	: GE61067368
Engine Capacity	: 1339 cc

The vehicle caught fire. The cause of fire probably due to short circuit. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 14,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 5,411.00)
Nett Liability	<u>S\$ 8,589.00</u> =====

Vehicle Inspected By:



CHUA KANG SENG
Licensed Appraiser



K.K.LAU
*MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust),MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE,MIMI,MSAE,MCI Ard, AM,NIJAAR(USA),
AM CATARI(CAN),M.MATA(USA),M.MdATA(USA),
Licensed Appraiser*

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.