

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 11 Jan 2022

Preliminary Advice

Vehicle No	: SLV9795Y	Accident Date	: 07/01/2022
Make	: HONDA FIT	Policy No.	: DMPG21010255
Assignment Date	: 10/01/2022	Excess	: S\$0.00
Date of Inspection	: 10/01/2022	Est. Duration of Repair	: 0
Inspection At	: JIN AUTO SERVICES PTE LTD (DEFU) BLK 14 DEFU LANE 10, #01-410/412 SINGAPORE 539195		

Point of Impact / General Description of Damages

Pending for investigation.

Repairer's Estimate (Gross)	:S\$	TOTAL LOSS
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	14,000.00

COE / PARF Rebate	:S\$	5,411.00
Salvage Value	:S\$	
Margin for Repair	:S\$	8,589.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

- (X) Other comments : PENDING FOR INVESTIGATION.