



SINGAPORE CIVIL DEFENCE FORCE

FIRE REPORT

1. GENERAL INFORMATION			
INCIDENT NO. : /20220107/1024	LOCATION OF FIRE:		
FIRE REPORTED ON : 07 January 2022	Along Tannery Road before Genting Lane		
TIME OF CALL : 22:12:44 hrs	(In front of 35 Tannery Road)		
STATION COVERAGE : Paya Lebar Fire Station	Singapore 347740		
2. INCIDENT INFORMATION			
FIRE INVOLVED: A Honda car (SLV9795Y).			
METHOD OF EXTINGUISHMENT: By a member of public using a dry powder fire extinguisher prior to the arrival of SCDF crew.			
PROBABLE CAUSE OF FIRE: Accidental (Electrical origin at the dashboard)			
DAMAGE SUSTAINED: As a result of the fire, the electrical wirings and electrical components within the enclosure of the dashboard were damaged. A section of the dashboard, windscreen, steering wheel, floor mat and other miscellaneous in the area sustained varying degrees of heat and smoke damage.			
The interior of the car sustained smoke damage.			
3. FATALITY/INJURY INFORMATION			
NAME	PIN/FIN	ADDRESS	DEAD/INJURIES SUSTAINED
NIL	NIL	NIL	NIL
REPORT CERTIFIED TRUE AND CORRECT BY:			
ANG LI FENG for COMMISSIONER SINGAPORE CIVIL DEFENCE FORCE			

This is a computer generated Fire Report. No signature is required.