

Not Authorized  
Lark  
10/11/22  
L/S \$3500/  
Hays

**GBE2766K Toyota Dyna**

| No                        | Qty | Parts Description                                     | Parts Price   |
|---------------------------|-----|-------------------------------------------------------|---------------|
| 1                         | 1   | Front bumper assy <i>waped 681.10</i>                 | \$ 1,012.00 ✓ |
| 2                         | 2   | Front bumper bracket <i>11</i>                        | \$ 230.00 X   |
| 3                         | 1   | Front bumper reinforcement <i>11</i>                  | \$ 496.00 X   |
| 4                         | 1   | Front grille assy <i>11</i>                           | \$ 468.00 X   |
| 5                         | 1   | Front grille emblem <i>11</i>                         | \$ 88.00 X    |
| 6                         | 1   | Front panel assy <i>11</i>                            | \$ 1,296.00 X |
| 7                         | 2   | Front panel bracket <i>11</i>                         | \$ 183.00 X   |
| 8                         | 1   | Front panel Dyna emblem <i>11</i>                     | \$ 68.00 X    |
| 9                         | 2   | Front panel lower mounting <i>11</i>                  | \$ 285.00 X   |
| 10                        | 1   | Front right <del>lower</del> corner panel <i>11</i>   | \$ 183.00 ✓   |
| 11                        | 1   | Front right upper corner panel <i>waped</i>           | \$ 484.00 ✓   |
| 12                        | 1   | Front right headlamp <i>scr</i>                       | \$ 696.00 ✓   |
| 13                        | 1   | Front centre garnish <i>11</i>                        | \$ 197.00 X   |
| 14                        | 1   | Front right side top garnish <i>(black) goad</i>      | \$ 108.00 ✓   |
| 15                        | 1   | Front right wing mirror <i>11</i>                     | \$ 298.00 X   |
| 16                        | 1   | Front towing hook <i>11</i>                           | \$ 179.00 X   |
| 17                        | 1   | Front right door panel assy <i>11/scr</i>             | \$ 1,467.00 ✓ |
| 18                        | 1   | Front right door regulator with motor assy <i>11</i>  | \$ 479.00 X   |
| 19                        | 1   | Front right door lock mechnaism <i>11</i>             | \$ 255.00 X   |
| 20                        | 2   | Front right door panel hinges <i>11</i>               | \$ 165.00 X   |
| 21                        | 1   | Front right door checker linkage <i>11</i>            | \$ 166.00 X   |
| 22                        | 1   | Front right door lower step inner panel <i>11</i>     | \$ 354.00 X   |
| 23                        | 1   | Front right door lower step garnish <i>scr 245.10</i> | \$ 277.00 ✓   |
| 24                        | 1   | Front windscreen glass moulding <i>11</i>             | \$ 288.00 X   |
|                           |     |                                                       | \$ 9,722.00   |
| Less 25%                  |     |                                                       | \$ 2,430.50   |
|                           |     |                                                       | \$ 7,291.50   |
| <u>Special Nett Items</u> |     |                                                       |               |
| 1                         | 6   | Front grille clips <i>11</i>                          | \$ 45.00 X    |
| 2                         | 1   | Front no plate <i>11</i>                              | \$ 100.00 X   |
| 3                         | 2   | Front right side top garnish clips <i>11</i>          | \$ 30.00 X    |
| 4                         | 4   | Front centre garnish clips <i>11</i>                  | \$ 30.00 X    |
| 5                         | 1   | Front right door compamy sticker <i>scr</i>           | \$ 80.00 30   |
| 6                         | 1   | Front right door advertisement sticker <i>scr</i>     | \$ 650.00 400 |
| 7                         | 1   | Front windscreen glass sealant <i>11</i>              | \$ 100.00 X   |
| 8                         | 1   | Front panel sticker <i>11</i>                         | \$ 350.00 X   |
| 9                         | 1   | Front panel sealant <i>11</i>                         | \$ 100.00 X   |
|                           |     |                                                       | \$ 1,485.00   |
| <b>Total parts</b>        |     |                                                       | \$ 8,776.50   |



**GBE2766K Toyota Dyna**

| No                    | Description                                                                                          | Labour Charges     |     |
|-----------------------|------------------------------------------------------------------------------------------------------|--------------------|-----|
| 1                     | Labour for panel beating, cut, weld, straighten front affected area and replace front damaged parts. | \$ 1,200.00        | 400 |
| 2                     | To putty and spray painting front portion.                                                           | \$ 1,200.00        | 550 |
| 3                     | To check wiring and focus front headlamp.                                                            | \$ 50.00           | 20  |
| 4                     | To transfer front right door glass to new door.                                                      | \$ 80.00           | 60  |
| 5                     | To apply anti rust proofing to front affected area.                                                  | \$ 140.00          | 30  |
| 6                     | To synchronise front right wing mirror for function.                                                 | \$ 80.00           | X   |
| 7                     | To remove and install front right door lock mechanism. <i>Repeated</i>                               | \$ 80.00           | X   |
| 8                     | To check door central locking for function.                                                          | \$ 80.00           | X   |
| 9                     | To remove and install front right door regulator with motor assy.                                    | \$ 80.00           | X   |
| 10                    | Towing service.                                                                                      | \$ 100.00          | X   |
| <b>Total labour :</b> |                                                                                                      | <b>\$ 3,090.00</b> |     |

**Total parts : \$ 8,776.50**

**Total labour : \$ 3,090.00**

**Total repair cost : \$ 11,866.50**

P-3864.20  
 282  
 P-2898.15  
 S.N-430  
 L-1060  
 4388.15  
 292  
 3510.52

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: