

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SLQ1063E
Accident Date : 01-Jan-2022
Our Ref : 022004 (CHINA) / CHAN

No. : 06511

Date : 06-Jan-2022

PAGE : 1

LEE HON CHUAN
66 TOH TUCK ROAD
#04-08
Singapore 596723

Not Authorized
11 Lm @
Repair After Paint
2 day

ESTIMATED COST OF REPAIR FOR TOYOTA CAMRY SME5908T

1 pc Rear bumper fascia
1 pc Rear bumper reinforcement
2 pcs Rear bumper reflector
2 pcs Rear bumper side retainer

@ S\$ 54.16
@ S\$ 58.20

Bu 580.30 ✓
BT 420.10 ✓
Bu 108.32 X
Bu 116.40 X

1,225.12

Less 25% : 306.28

1 pc Rear bumper reverse sensor

918.84 200/200
Short 300.00 sn

To putty and spray replaced parts

300.00 *200d*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

300.00 *200d*

Total : S\$ 1,818.84

Singapore Dollars One Thousand Eight Hundred
and Eighteen and Cents Eighty Four Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: