



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2203439
INV Date 06/06/2022
Reference CC4/LPC22000304/Gga3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SMC 2938L
Insured Veh. SKJ 2770P
Claim No. 21/22/22/VP05/025348
Policy No. Z21VP05028674
Accident Date 09/01/2022
Inspection Date 11/01/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Ref: CC4/LPC22000304/Gga3q2 Date: 06/06/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKJ 2770P	Veh. Inspected	SMC 2938L
Policy No.	Z21VP05028674	Coverage (\$)	0.00
Claim No.	21/22/22/VP05/025348	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	10/01/2022
2. Vehicle Particulars & Condition			
Make & Model	HONDA VEZEL 1.5X	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	RU11302983	Colour	BLUE
Odometer	120402 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	BRIDGESTONE	6 mm
L/H Front Tyre	215/60 R16	BRIDGESTONE	6 mm
R/H Rear Tyre	215/60 R16	BRIDGESTONE	6 mm
L/H Rear Tyre	215/60 R16	BRIDGESTONE	6 mm
4. Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.		
5. General Information			
Accident Date	09/01/2022	Inspection Date	11/01/2022
Survey held at	AUTO BULLOX PTE LTD 53 UBI AVENUE 1 #01-25 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		
5a. Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
5b. Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMC 2938L

Qty	Description of Parts	Condition	Initial Surveyor (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT GRILLE ASSY	SCRATCHED	900.00	397.00
1	FRONT GRILLE EMBLEM	NECESSARY	45.00	38.80
1	FRONT BUMPER	DEFORMED	902.00	902.00
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	80.00	-
2	FRONT BUMPER RETAINER	DEFORMED (1 PCS ONLY)	148.00	44.00
1	FRONT BUMPER REINFORCEMENT	BENT	371.00	321.00
1	FRONT HEADLAMP LH	SCRATCHED	2,150.00	1,284.50
1	FRONT HEADLAMP TOP CHROME MOULDING LH	NOT NECESSARY	156.00	-
1	FRONT FOG LAMP LH	SCRATCHED	341.00	189.00
1	FRONT FOG LAMP COVER LH	CUT	108.00	98.00
1	FRONT FENDER LH	NOT NECESSARY	689.00	-
1	FRONT FENDER INNER SHIELD LH	NOT NECESSARY	115.00	-
1	FRONT FENDER SIDE GARNISH LH	NECESSARY	291.00	150.20
1	FRONT SUPPORT PANEL	NOT NECESSARY	641.00	-
	LESS 20% DISCOUNT		-1,387.40	-684.90
			5,549.60	2,739.60
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	30.00	30.00
1	SET FRONT GRILLE CLIP (SN)	NECESSARY	20.00	20.00
1	SET FRONT FENDER INNER SHIELD CLIP (SN)	NOT NECESSARY	30.00	-
			80.00	50.00
<u>LABOUR</u>				
	CHECK FRONT WIRING AND LIGHTING SYSTEM.		60.00	30.00
	PANEL BEATING AND RENEW DAMAGE PARTS ON AFFECTED AREAS .		800.00	300.00
	SPRAY PAINTING ON AFFECTED AREAS.		800.00	200.00
	APPLY ANTI RUST ON AFFECTED AREAS .	NOT NECESSARY	120.00	-
			1,780.00	530.00
GRAND TOTAL			7,409.60	3,319.60



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		0.00	2,650.00
---	--	-------------	-----------------

Report Ref No. CC4/LPC22000304/Gga3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMC 2938L

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

