

Date: 03.01.2022  
 Vehicle No: SLD8081A  
 Model: TESLA MODEL 3 PERFORMANCE  
 Chassis: LRW3F7EL5MC263562  
 Reg.Year: 2021

Third Party Insurer: EQ  
 Third Party Veh No: SNB4444A  
 Date of Accident: 31.12.2022  
 Estimator: Victor  
 Surveyor:

**ESTIMATE**

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT DOOR RH	1		\$1,009.35
SUB TOTAL				\$1,009.35
LESS 10%				-\$100.94
PARTS TOTAL				\$908.42

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	CERAMIC COATING	1		\$500.00
S/N TOTAL				\$500.00

**LABOUR CHARGES:**

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR & READJUST ACCIDENT AREA. \$400.00 *sd*

LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREA. \$400.00 ✓

TO CHECK WIRING & ELECTRICAL SYSTEM. *nn* \$150.00 X

TO DIAGNOS FAULT CODE & RESET MEMORY. *nn* \$200.00 X

*Not Authorized*

LABOUR TOTAL \$1,150.00

**TOTAL \$2,558.42**

*2 days  
\$600*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_