


Make/Model: HONDA CIVIC 1.6A
 Engine/Chassis No.: MRHFC5650GT001108
 Date of accident:
 Damaged area: O/S

Date: 11/01/2022
 Claim Type: TP
 VRN: SLM812M

*Not authorized
 11/01/22 00h
 Penny After Rain*



4 days

List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear fender o/s	1	\$ 902.00	\$ 902.00
2	Rear fender cowling o/s	1	\$ 185.00	\$ 185.00
3	Rear bumper <i>217-20</i>	1	\$ 876.00	\$ 876.00
4	Rear bumper reflector o/s	1	\$ 189.00	\$ 189.00
5	Rear bumper reflector garnish o/s	1	\$ 145.00	\$ 145.00
6	Rear bumper retainer	2	\$ 85.00	\$ 170.00
7	Rear knuckle carrier o/s	1	\$ 498.00	\$ 498.00
8	Rear knuckle carrier bearing o/s	1	\$ 145.00	\$ 145.00
9	Rear upper control arm o/s	1	\$ 286.00	\$ 286.00
10	Rear lower control arm o/s	1	\$ 329.00	\$ 329.00
11	Rear end link o/s	1	\$ 136.00	\$ 136.00
12	Rear shock absorber o/s	1	\$ 345.00	\$ 345.00
13	Rear shock absorber top mount o/s	1	\$ 63.00	\$ 63.00
Subtotal				\$ 4,269.00
List discount				20.00%
Total				\$ 3,415.20

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Sundries	1	\$ 50.00	\$ 50.00
2	Rear alloy wheel o/s	1	\$ 450.00	\$ 450.00
3	Rear tyre o/s	1	\$ 180.00	\$ 180.00
4	Rear fender cowling o/s clips	8	\$ 5.50	\$ 44.00
5	Rear bumper clips	10	\$ 5.50	\$ 55.00
Total				\$ 779.00

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew the accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	6	\$ 1,200.00
	To computerized 4 wheel alignment.	0.5	\$ 100.00

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

acknowledged by Repairer
 Signature:
 Date:

Repair Estimate

3	To remove and refit o/s rear undercarriage for replacement of parts.	1	\$ 200.00
4	To remove and refit o/s rear tyre & rim for replacement. To perform tyre balancing.	0.25	\$ 50.00
5	Supply spray paint material and necessary items to respray affected area / panel.	5	\$ 1,000.00
6	To rust proof all affected portions after repair.	0.5	\$ 100.00
Total labour			\$ 2,650.00

Estimate Grand Total

6 RAA 201