

ASS. REC. BY:

REF:

cs/cn 22000308/Kv

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMG 789Sat Workshop m/s EM Solutionof 978C

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP / 24 HRS

Date: 08/30 Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMG 789S Yr Regn: 08, 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or MPVMake: Toy Wish c.c. 1987Colour M. Grey A/C: Insured / Std / NI / NASp. Reading 215607 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDGJ20W705002519Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 225/45R17BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

R/Bal. 8 mmL/Bal. 8 mmD.O.A. 6/1/22

Rear

R/Bal. 8 mmL/Bal. 8 mmD.O.I. 11/1/22

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Got BZ

Date/Time, File Pass to?

☐ : Preli. Report1) _____
Date/Time, File Return to?☐ : Final Report

2) _____

Rep. Form:

Lump Sum / B.C.:

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. SI

Photos

Others

TOTAL

E M SOLUTION PTE LTD

160 Sin Ming Drive #03-18/19, Sin Ming Autocity
Singapore 575722

Tel: 64560226 Fax: 64584500

GST Reg. No: 201016308K

ESTIMATE

Date : 10th January 2022

Mr **Ang Freddy**
Blk 325 Tah Ching Road, #16-34
Singapore 610325

Veh No : **SMG 789S**
Make/Model : **Toyota Wish**
Chassis No : JTDGJ20W705002519
Date of Acc : 06.01.21
TP Veh No : SLR 6308L

S/No	Qty	Description	Unit Price	Amount
Materials				
1	1 pc	Rear Tailgate <i>BT</i>		
2	2 pcs	Rear Tailgate Lamp L/R <i>N/S CM LT</i>		
3	1 pc	Rear Tailgate No Plate Garnish <i>mx</i>		
4	1 set	Rear No Plate Lamp <i>mx</i>		
5	1 pc	Rear Tailgate Toyota Logo <i>mx</i>		
6	1 pc	Rear Tailgate Inner Trimboard <i>?</i>		
7	1 pc	Rear Tailgate Mechanism Lock <i>mx</i>		
8	1 pc	Rear Boot Weatherstrip <i>mx 5065m</i>		
9	1 pc	Rear Windscreen Inner Seal <i>mx 301m</i>		
10	2 pcs	Rear Lamp L/R <i>N/S Brolt</i>		
11	1 pc	Rear Lamp Panel LH <i>BT</i>		
12	1 pc	Rear Fender LH <i>BT</i>		
13	1 pc	Rear Fender Inner Upholstry LH <i>Return</i>		
14	1 pc	Rear Fender Liner LH <i>?</i>		
15	1 pc	Rear Fender Petrol Tank Panel <i>?</i>		
16	1 pc	Rear Fender Quarter Glass Moulding <i>mx</i>		
17	1 pc	Rear Bumper <i>BT</i>		
18	2 pcs	Rear Bumper Side Holder L/R <i>N/S CM LT</i>		
19	2 pcs	Rear Bumper Bracket L/R <i>N/S BT LT</i>		
20	1 pc	Rear Bumper Reinforcement <i>x</i>		
21	2 pcs	Rear Bumper Reflector L/R <i>CM</i>		
22	1 pc	Rear End Panel <i>BT</i>		
23	1 pc	Rear End Panel Top Garnish <i>mx</i>		
24	1 pc	Rear Chassis Member LH <i>mx</i>		

	\$	-
Less 25%	\$	-
Parts Total :	\$	-

Special Nett

1	1 set	Rear Bumper Clips	\$	<i>mx</i>	45.00	<i>—</i>
2	1 set	Rear End Panel Garnish Clips	\$	<i>mx</i>	35.00	<i>—</i>
3	1 set	Rear Fender Liner Clips	\$	<i>mx</i>	35.00	<i>—</i>
4	1 set	Tailgate Inner Trim Clips	\$	<i>mx</i>	35.00	<i>—</i>
5	1 set	Tailgate Auto Switch				<i>?</i>
6	1 set	Reverse Sensor	\$	<i>mx</i>	300.00	<i>2005m</i>
7	2 pcs	Windscreen Sealant	\$	<i>mx</i>	100.00	<i>405m</i>

Special Nett : _____

Labour

1	To remove & rearrange electrical wirings, check lightings	\$	80.00	200
2	To remove & replace upholstery, cushion seat & trim garnishes.	\$	150.00	1000
3	To remove, instal rear windscreen.	\$	150.00	1200
4	To remove, transfer tailgate components	\$	100.00	600
5	To remove, instal rear fender quarter glass	\$	100.00	500
6	To remove, instal petrol tank to facilitate repairs.	\$	150.00	500
7	To remove, repair & replace damaged bodyparts and where consistent to the accident.	\$	2,200.00	12000
8	Putty and respray painting on affected portions.	\$	1,800.00	10000
9	To remove & renew reverse sensor	\$	150.00	500
10	Rust proofing on affected portions.	\$	100.00	900

Labour Total :

Total Parts & Labour :

\$ -



for E M Solution Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	07/01/2022 14:20 (SGT)
Date of Accident	06/01/2022 21:20 (SGT)
Exact Location of Accident	AYE, Singapore
Additional Location Information	Clementi Ave 6 filter lane to AYE towards city
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMG789S
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	Ang Freddy
NRIC No	S7622978C
Email Address	fredbkk789@gmail.com
Mobile Phone No	(Phone) +65-87888789
Alternative Phone No	(Home) +65-87888789

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Wish
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private hire
Transmission	Auto
CC	1800

INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5118568232-01
Cover Note Number	-

DRIVER

Name of Driver	Ang Freddy
NRIC No	S7622978C



SINGAPORE POLICE FORCE

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20220107/7006

1 of 3

Report No. T/20220107/7006

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:
07/01/2022 11:52

Vide Report No.:

Station Diary No.:

Informant's Particulars

Name of Informant:
ANG FREDDY

Address:
325 TAH CHING ROAD #16-34 SINGAPORE 610325

ID Type / ID No.:
NRIC NO / S7622978C

Contact No.:
Home/Office: Mobile: 87888789

Nationality:
SINGAPORE CITIZEN

Email:
FREDBKK789@GMAIL.COM

Sex: Age: Date of Birth:
Male 45 23/07/1976

Type of Informant:
Vehicle Owner

Race:
Chinese

Language: Institution / School Name:
English

Occupation:
Self Employed

Driving Licence Information:
Class: 2B,2A,2,3,4,5 Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 06/01/2022 21:20	Type of Location: Slip Road
-------------------	---------------	-----------------	---	-----------------------------

Location:

AYER RAJAH EXPRESSWAY

Weather:
Clear

Road Surface:
Dry

Road Speed Limit:
60 Km/h

Traffic Flow:
One Way

Traffic Control:
Not Controlled

Traffic Volume:
Light

Type of Collision:
Between Moving Vehicles - Head To Rear

Anyone conveyed by ambulance:
No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Conditio	No of
SLR6308L	Car	LEXUS		Black	Seriously Damaged	0
SMG789S	Car	TOYOTA	Wish	Grey	Seriously Damaged	0

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20220107/7006

2 of 3

Report No. T/20220107/7006

CONTINUATION OF REPORT

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SMG789S	NTUC Income Insurance Co-Operative Limited	5118568232-01	27/08/2021	26/08/2022

Details of Person Involved

Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Vehicle Owner			
Name	ANG FREDDY	ID No.	S7622978C
Related Vehicle	SMG789S (Car)	Contact No.	87888789
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry	Class: 2B,2A,2,3,4,5 Date of Expiry: NIL
Date	07/01/2022	Date	07/01/2022
No. of Days granted Medical Leave	07	Degree of	Serious

Brief Details.

I stopped my car SMG789S at the slip road junction waiting for traffic along AYE to clear. A few seconds later, I felt a strong impact on the rear of my car forcing my car to surge forward into the main road (AYE). Veh No. SLR 6308L had collided onto the rear of my car. Thereafter, we alighted and exchange particulars. I consulted the doctor and was given 7 days MC.