

Date: 07/01/2022
Vehicle No: SMN1272Y
Model: MERCEDES BENZ E200
Chassis: WDD2130422A538780
Reg.Year: 2019

Not Authorized
Mervey B Repair
3 day
11 Pmp @ 3050/e

Third Party Insurer: AIG
Third Party Veh No: SMD8625U
Date of Accident: 06/01/2022
Estimator: KIT
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER <i>1613</i>	1	<i>Bur</i>	\$2,250.00 ✓
2	REAR BUMPER SIDE RETAINER LH	1	<i>Pr</i>	\$85.00 X
3	REAR BUMPER SIDE RETAINER RH	1	<i>Pr</i>	\$85.00 X
4	REAR BUMPER LOWER BUMPER	1	<i>Pr</i>	\$445.00 ✓
5	REAR BUMPER LOWER CHROME MOULDING <i>315</i>	1	<i>mgc mt</i>	\$365.00 ✓
6	REAR BUMPER REVERSE SENSOR	2	<i>Shon \$220.00</i>	<i>Pr</i> \$440.00 ✓
7	REAR BUMPER REFLECTOR LH	1	<i>mgc mt</i>	<i>Pr</i> \$65.00 X ✓
8	REAR BUMPER REFLECTOR RH	1	<i>Pr</i>	\$65.00 X
9	REAR EXHAUST TIP CHROME LH	1	<i>Pr</i>	\$190.00 X
10	REAR EXHAUST TIP CHROME RH	1	<i>Pr</i>	\$190.00 X
11	REAR REINFORCEMENT	1	<i>Pr</i>	\$600.00 ✓
12	END PANEL	1	<i>Pr</i>	\$750.00 X
13	END PANEL TOP COVER	1	<i>Pr</i>	\$140.00 X
14	BOOTLID	1		REPAIR
SUB TOTAL				\$5,670.00
LESS 10%				-\$567.00
PARTS TOTAL				\$5,103.00

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	1		<i>Pr</i> \$100.00 ✓
2	REAR END PANEL JOINT SEALANT	1		<i>Pr</i> \$120.00 X
3	REAR BUMPER CHROME MOULDING CLIPS	1		<i>Pr</i> \$40.00 ✓
4	END PANEL TOP COVER CLIPS	1		<i>Pr</i> \$50.00 X
S/N TOTAL				\$310.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT \$700.00 *250*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER, REAR END PANEL & ETC. \$800.00 *220*

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC. \$120.00 *60*

TO DAIGNOSIS FAULT CODE & RESET MEMORY. *Pr* \$120.00 X

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 07/01/2022
 Vehicle No: SMN1272Y
 Model: MERCEDES BENZ E200
 Chassis: WDD2130422A538780
 Reg.Year: 2019

Third Party Insurer: AIG
 Third Party Veh No: SMD8625U
 Date of Accident: 06/01/2022
 Estimator: KIT
 Surveyor:

TO TUFF COAT AND UNDERSEAL MATERIAL.

~ \$120.00 X

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

\$100.00 15/2

LABOUR TOTAL \$1,960.00

TOTAL \$7,373.00

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

