

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

JACQUELINE TAN SI HUI
BLK 592C MONTREAL LINK #16-30
SINGAPORE 753592

TP Budget Direct.
Veron.

TAX INVOICE

Repair Code : CLM15409

Date in : 08/01/2022

Vehicle Num. : SJS-749D

Model : HONDA CIVIC 1.8L A

Chassis/Eng# : JHMFD16306S208107/R18A11027161

Contact : 91186196

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
AIRCON CONDENSER <i>Revised</i>	1	729.40	✓ 729.40
AIRCON CONDENSER ALUMINIUM PIPE <i>Best</i>	1	178.90	✓ 178.90
AIRCON CONDENSER DISCHARGE PIPE <i>new</i>	1	201.80	+ 201.80
AIRCON FAN BLADE <i>new</i>	1	58.40	+ 58.40
AIRCON FAN COWLING <i>new</i>	1	85.00	+ 85.00
AIRCON FAN MOTOR <i>new</i>	1	294.50	+ 294.50
EXHAUST MANIFOLD COVER <i>Revised</i>	1	69.00	✓ 69.00
FRONT BONNET HINGES L/R <i>new</i>	2	38.90	+ 77.80
FRONT BONNET MECHANISM LOCK <i>Revised</i>	1	85.00	✓ 85.00
FRONT BUMPER <i>Discontinued</i>	1	658.00	✓ 658.00
FRONT BUMPER NUMBER PLATE GARNISH <i>Revised</i>	1	51.40	✓ 51.40
FRONT BUMPER REINFORCEMENT <i>Revised</i>	1	258.10	✓ 258.10
FRONT BUMPER RH FOGLAMP <i>Checked</i>	1	303.80	✓ 303.80
FRONT BUMPER RH FOGLAMP GARNISH <i>new</i>	1	85.70	✓ 85.70
FRONT BUMPER SIDE RETAINER L/R <i>new</i>	2	16.00	✓ 32.00
FRONT GRILLE TOP GARNISH <i>Checked</i>	1	165.20	✓ 165.20
FRONT HEADLAMP L/R (H.I.D) <i>Checked</i>	2	912.10	✓ 1,824.20
FRONT HEADLAMP LOWER BRACKET L/R <i>RH Best</i>	2	35.30	35.30 ✓ 70.60

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 41 7921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

JACQUELINE TAN SI HUI
 BLK 592C MONTREAL LINK #16-30
 SINGAPORE 753592

Contact : 91186196

TAX INVOICE

Repair Code : CLM15409
 Date in : 08/01/2022
 Vehicle Num. : SJS4749D
 Model : HONDA CIVIC 1.8L A
 Chassis/Eng# : JHMFD16306S208107/R18A11027161

FRONT RH FENDER	<i>Replaced</i>	1	537.50	✓	537.50
FRONT RH FENDER BRACKET	<i>new</i>	1	38.00	+	38.00
FRONT RH FENDER INNER SHIELD	<i>Del'd</i>	1	98.00	✓	98.00
FRONT RH FENDER TOP GARNISH	<i>new</i>	1	26.70	+	26.70
FRONT RH HEADLAMP H.I.D BALLAST	<i>replaced</i>	1	340.40	✓	340.40
FRONT RH HEADLAMP H.I.D BULB	<i>new</i>	1	344.70	+	344.70
FRONT SUPPORT PANEL	<i>Replaced</i>	1	470.00	✓	470.00
POWER STEERING OIL PIPE	<i>new</i>	1	221.00	+	221.00
RADIATOR (A)	<i>Best</i>	1	1650.50	✓	1650.50
WASHER TANK	<i>Del'd</i>	1	62.90	✓	62.90
WASHER TANK MOTOR	<i>new</i>	1	61.40	+	61.40
Subtotal before discount					9,079.90
Percentage discount 20%					1,815.98
Sub-total I					7,263.92
FRONT BONNET	<i>Del'd</i>	1	2200.00	<i>1200</i> ✓	2,200.00
FRONT BONNET MOULDING	<i>new</i>	1	200.00	<i>100</i> ✓	200.00
FRONT BUMPER CLIPS - SET	<i>new</i>	1	50.00	<i>30</i> ✓	50.00
FRONT GRILLE	<i>Replaced</i>	1	400.00	<i>300</i> ✓	400.00

7364.80
5891.84

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

JACQUELINE TAN SI HUI
 BLK 592C MONTREAL LINK #16-30
 SINGAPORE 753592

Contact : 91186196

TAX INVOICE

Repair Code : CLM15409
 Date in : 08/01/2022
 Vehicle Num. : SJS4749D
 Model : HONDA CIVIC 1.8L A
 Chassis/Eng# : JHMFD16306S208107/R18A11027161

FRONT GRILLE 'LOGO' EMBLEM <i>new</i>	1	100.00	<i>50</i>	100.00
FRONT GRILLE CLIPS - SET <i>new</i>	1	30.00	<i>20</i>	30.00
FRONT HEADLAMP PROTECTION STICKER L/R <i>new</i>	2	200.00	<i>160</i>	400.00
FRONT RH FENDER INNER SHIELD CLIPS - SET <i>new</i>	1	50.00	<i>30</i>	50.00
FRONT RH FOGLAMP BULB <i>new</i>	1	250.00	<i>1970</i>	250.00
FRONT RH FOGLAMP PROTECTION STICKER <i>new</i>	1	100.00	<i>40</i>	100.00
POWER STEERING FLUID <i>new</i>	1	40.00	<i>+</i>	40.00
RADIATOR COOLANT <i>new</i>	1	60.00	<i>40</i>	60.00
Subtotal before discount				3,880.00
Percentage discount 0%				0.00
Sub-total 2				3,880.00
Parts-total				11,143.92

LABOUR

- To remove, change air con parts, vacuums, refill air con gas.
- To remove, reinstall electrical wiring harness, check lighting. (to FR)
- To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.
- To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.
- To apply anti-rust chemical on repaired and replaced panel.

<i>1710</i>	<i>120</i>	150.00
	<i>30</i>	60.00
	<i>900</i>	1,100.00
	<i>800</i>	1,200.00
	<i>60</i>	80.00
Labour Total		2,590.00
Parts & Labour Total		13,733.92

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

This is a computer-generated document which requires no signature.

Admin
11/01/22
L/S 06 Days
 total: *9571.84*
 H/s: *7.6K* ✓