

	Date	No.
Rear Boot Lid Distorted	1782.40	✓
Rear Boot Lid ^{Hinge} Brackets 2x \$94.30 Set	188.60	✓
" " Lock Jammed	116.20	✓
" " Rubber Lt	95.20	✓
" " Emblem (H) New	27.98	✓
" " " Elantra New	8.80	✓
" " Lamp 2x \$284.90 Cashed	569.80	✓
Rear Number Plate Lamp 2x \$21.00	42.00	X
Rear Fender RH Repair	1768.30	X
" " Lamp 2x \$362.60 Cashed	725.20	✓
Rear Boot Lid Inner Cover - Crumpled	146.80	✓
Rear Bumper - Distorted	459.40	✓
" " Side Molding 2x \$44.30	88.60	✓
" " Box Reflector 2x \$32.90 Cashed	65.80	✓
" " clip 11x \$4.90 New	53.90	30
Rear Bumper Reinforcement Distorted	320.60	✓
Rear Lower Bumper Deformed	250.10	✓
Rear Bumper Reinforcement	—	
Rear End Panel Distorted	454.60	✓
" " Panel Top Garnish Cove Deformed	59.80	✓
Rear spare Tyre Fank Panel Repair	640.80	X
Rear Bumper Low Cover LH New	260.20	X
Rear Exhaust Bent	688.40	✓
Rear Reverse sensor - Dangled	350	200(SN)
Side Fender garnish 2x \$207.90 torn	415.80	✓
Tyre Floor xbol New	219.10	X
	9483.38	
	Less 20%	
	1896.67	
	7586.71	

Date	No	
	1741	Front Bonnet Dented 1910.30
	X	" " Hinge 2x 49.10 Nt New 98.20
	✓	" " Lock Dump 129.90
	X	" " Insulator Nt New 221.10
	X	" " Insulator - dip 14x 5.90 82.60
	✓	Front Bumper Dented 474.40
	✓	Front Bumper side Retainer 2x 28.50 56.00
	X	" " side small grille 2x 35.00 70.00
	✓	Front Grille Assy } Cracked 529.50
	X	" " Emblem } 31.40
	X	Front Bumper Rubber Nt New 31.40
	845	Front Support Panel Cracked 949.30
	X	" " Panel Top garnish Cover Nt New 78.10
	X	" " Panel Top garnish dip 6x 49.00 29.40
	✓	Head Lamp Assy RH/LH 2x 1198.80 Cracked 2397.60
	515	Front Bumper Reinforcement Dented 695.80
	X	" " Lower Cover Nt New 63.70
	X	Radio to Ref. Nt New 85.10
		7902.40
		Less 20% 1580.48
		6321.92

Parts: 13182.48

Less 20%: 10545.98

S.N: 200

Date	No
From pg ①	7586.71
From pg ②	6321.92
Front / Rear Number plate & 50 x 2 ^{Realt}	100.00 ✓
To dismantle exhaust Pipe	150.00 80
To remove cushion	80.00 ✓
To check wiring	120.00 60
Panel beating & replace parts - Front	1050.00 600
Panel beating & replace parts - Rear	1800.00 1000
Spray painting Front / Rear parts	1600.00 1400
	18,808.63

3300.

Jump Jam! #15,046/77

Total: 14065.98

2/5: 11.2K

12 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: