

TPAXA

Xiao Chan.

GBE3547U 2015 Nov

Toyota Dyna 2982cc

JTFAT35Y10K205169.

Side Gate RH

Dented

1409.40 /

Side Gate Advertiser Sticker

run

~~500~~ 450 (sw)

Side Gate Hinge x 03

NP
run

66.3 x 3 = 198.90
x

Rear Wheel Panel (Front) RH

Repair

245.90.

Rear Wheel Panel (Rear) RH.

Repair

250.40.

1409.40

S.N: 450

1057.05

Panel Beating

780.

~~600~~ 200

Spray Painting

~~600~~ 500

To remove side gate railing.

~~180~~ 80.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

knowned by Repairer

Total: 2287.05

H/S: 1.8K.

02 Days.