



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: KHOR SAW THENG			Ref: CS/ASM22000344/Aqy3e2 Date: 29/03/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMK 6923K	Veh. Inspected	GBE 3547U
	Policy No.	VPA/P2278364	Coverage (\$)	0.00
	Claim No.	S1M03PMA	Excess (\$)	0.00
	Assign From	KHOR SAW THENG	Assign Date	11/01/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA DYNA	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	JTFAT35Y10K205169	Colour	WHITE
	Odometer	285032 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15C	ROVELO	6 mm
	L/H Front Tyre	195 R15C	ROVELO	6 mm
	R/H Rear Tyre	155 R12C	HABILEAD	6 mm
	L/H Rear Tyre	155 R12C	HABILEAD	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	27/12/2021	Inspection Date	05/02/2022
	Survey held at	JEC AUTO SERVICE PTE LTD 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	