

SMZ 236X 2021 April

TPA16.

Toyota Corolla Hybrid. 1798cc

Xiao Tony

JTDBB3BE00J030252

Front Bumper	torn	657.60 ✓
Front Bumper Clips	new	30(SN) ✓
Front Bumper Side Holder RH.	new	68.20 ✓
Headlamp RH.	cracked.	3557.10 ✓
Front RH Fender	Dented	791.80 ✓
Front RH Fender Inner Shield	NP new	188.70 X
Front RH Fender Inner Shield Clips	NP new	30(SN) X.
Front RH Fender Emblem.	new	69.60 ✓
Front RH Wing Mirror	NP new	1374.90 X
Front RH Wing Mirror Cover	Crackd	138.90 ✓
Front RH Wheel Rim	at	1995.20 850(SN)
Front RH Tyre.	xHP new	280(SN) X
Front RH Shock Absorber	NP new	787.60 X

SMZ236X

Front RH lower Arm. Best 805.10 550
Front RH Knuckle Arm. H 703.50 X
Front RH Wheel Hub clw Bearing. Dmnd 709.60 420.

6253.20

4689.80

S.N. 880

Panel Beating

~~700~~ 500

Spray Painting

1380

~~600~~ 500

Wiring.

~~50~~ 30

To perform wheel alignment

~~150~~ 80

To dismantle front undercarriage.

~~380~~ 200

total: 6879.80

f/s: S.S.K

05 Dm

(S.S.K)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: