

TPALG.
Xfaw Tery

YP8480P. 2015 March.

Isuzu NQR75 5193cc

JAA N1R7SKET100375.

Hydraulic Pump Repair

3600 X.

To repair and adjust rear
towing mechanism.

~~1000.~~ 700

To spray paint rear tow hook

~~400.~~ 300

total: 1000

02 Dyp.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: