

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SLN6700H
Accident Date : 08-Jan-2022

No. : 06518

Date : 10-Jan-2022

Our Ref : 022010 (EQ) / CHAN

PAGE : 1

SOH CHUAN SENG TIMOTHY
BLK 319 SERANGOON AVE 2
#02-354
Singapore 550319

*Not Authored
L1 Reg & 3800h
Recovery After Paint*

6 days

ESTIMATED COST OF REPAIR FOR TOYOTA WISH SLU6079G

1 pc Tail gate	1272	R	1,477.30	✓
1 pc Tail gate glass moulding-top		na	43.50	✓
1 pc Tail gate glass moulding-low		na	31.30	✓
2 pcs Tail gate glass side seal	@ S\$ 35.30	na	70.60	✓
1 pc Tail gate outer chrome		na	173.90	X
1 pc Tail gate logo		na	66.20	✓
1 pc Tail gate inner trim cover		na	328.20	✓
1 pc Tail gate inner lock		na	361.60	✓
1 pc Tail gate rubber		na	302.60	✓
2 pcs Tail gate lamp	@ S\$153.10	na	306.20	X
1 pc Rear end panel		na	453.90	✓
1 pc End panel top garnish		na	253.20	✓
1 pc Rear floor panel		na	543.20	✓
1 pc Rear bumper fascia		na	491.90	✓
2 pcs Rear bumper bracket	@ S\$ 48.40	na	96.80	✓
2 pcs Rear bumper side retainer-L	@ S\$ 89.90	na	179.80	X
2 pcs Rear bumper side retainer-S	@ S\$ 40.10	na	80.20	✓
1 pc Rear floor panel top cover		na	562.90	✓
			5,823.30	
	Less 25% :		1,455.82	

151.30

50% 15340.50

- 1 pc Rear bumper reverse sensor(set)
- 1 pc Rear w/s glass sealant
- 1 pc Rear no.plate with box
- 1 pc Rear bumper clip (set)

*na 4,367.48 200%
na 300.00 sn
na 400 60.00 sn
na 450 60.00 sn
na 40.00 sn*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.
Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N
GST Reg. No.: 201113667N

Vehicle Insured : SLN6700H

Page : 2

To remove & refix rear windscreen glass and conduct water leak test.	150.00	120
To remove roof lining, front and rear seats, trim board and carpet	120.00	60
To apply undersealing	80.00	60
To remove and renew exhaust silencer box	60.00	1
To putty and spray replaced parts	1,200.00	800
To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts	1,000.00	700
Total :	S\$ 7,437.48	

Singapore Dollars Seven Thousand Four Hundred and Thirty Seven and Cents Forty Eight Only