

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22000371/GTY3N2**Date:** 10/03/2022**REFERENCE**Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00005992103

**Claimant Vehicle  
No :** FBL3104C**Insured Vehicle  
No :** SLV6250Y

Date of Loss: 12/12/2021

Nature of Claim: TP

Claim  
No: SNM21D207236/C02/IRENE**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **FBL3104C**

Make &amp; Model: YAMAHA SNIPER T150, 150cc

Engine No: G3E6E0215471

Reg. Date: 17/08/2016 (Man. Year: 2016)

Chassis No: MH3UG0740G0026975

Colour: Black

Odometer: 0 km

Engine Capacity: 150 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	90/80-17	Rear Tyre Size:	100/80-17
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,020.00	1,782.00	238.00	11.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,250.00	640.00	610.00	48.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>3,270.00</b>	<b>2,422.00</b>	<b>848.00</b>	<b>25.93</b>

**INSPECTION**

Date of Assignment: 11/01/2022

Date Inspected: 12/01/2022 Inspected At:

 RF MOTOR PTE LTD (HQ)  
 NO. 8 KAKI BUKIT AVE 4 #06-24  
 PREMIER@KAKI BUKIT (GATE2) SINGAPORE  
 415875  
 Singapore RODNEY FOO

Estimated Period of Repair: 3.0 days

**Adjuster:** XING GUO QIANG**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 10 Mar 2022)	
<b>Parts:</b>	N/A	YAMAHA SNIPER T150 150cc (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBL3104C)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FAIRING	Cut	600.00 F	*600.00 FL
2	1		*EXHAUST	Cut	350.00 F	*350.00 FL
3	1		*EXHAUST COVER	Cut	60.00 F	*60.00 FL
4	1		*FRONT RIGHT SIGNAL	Cut	30.00 F	*30.00 FL
5	1		*HEADLIGHT	Broken	70.00 F	*70.00 FL
6	1		*LAMPSTAY	Bent	50.00 F	*50.00 FL
7	1		*HANDLE BAR	Bent	40.00 F	*40.00 FL
8	1		*LEFT/RIGHT LEVER	Cut	40.00 F	*40.00 FL
9	1		*LEFT/RIGHT MIRROR	Cut	50.00 F	*50.00 FL
10	1		*FOOT REST & MOUNT	Bent	80.00 F	*80.00 FL
11	1		*GEAR SHIFTER	Bent	40.00 F	*40.00 FL
12	1		*BRAKE PEDAL	Cut	40.00 F	*40.00 FL
13	1		*LEFT ENGINE COVER/GASKET	Cut	100.00 F	*100.00 FL
14	1		*FRONT WHEEL SHAFT/NUT	Not Necessary	40.00 F	*- FL
15	1		*FORK CLAMP/STEM/STEERING CONE	Bent	180.00 F	*180.00 FL
16	1		*FORK	Bent	250.00 F	*250.00 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,020.00</b>	<b>1,980.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	0.00	198.00
<b>Total Parts (\$\$)</b>	<b>2,020.00</b>	<b>1,782.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TOWING	New	50.00	40.00
2	LABOUR (ALIGNMENT CHECK)	New	200.00	100.00
3	LABOUR	New	1,000.00	500.00
<b>Gross Labour Cost (\$)</b>			<b>1,250.00</b>	<b>640.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >