



RF MOTOR PTE LTD

8 Kaki Bukit Ave 4, #06-24, Premier @ Kaki Bukit, Singapore 415875

Tel: +65 9177 7178 Email: rfmotorpl@gmail.com


Date: 27 Jan 2022

LKK Auto Consultants Pte Ltd
51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore (408933)

Attention: To Whom It May Concern

Dear Sir,

RE: Estimated Workshop Repair Fee for Vehicle - FBL3104C



No.	Description	Price	
1	Fairing ✓ CUT	\$600.00	✓
2	Exhaust ✓ CUT	\$350.00	✓
3	Exhaust Cover ✓ CUT	\$60.00	✓
4	Front Right Signal ✓ CUT	\$30.00	✓
5	Headlight ✓ BR	\$70.00	✓
6	Lampstay ✓ BT	\$50.00	✓
7	Handle Bar ✓ BT	\$40.00	✓
8	Left/Right Lever ✓ CUT	\$40.00	✓
9	Left /Right Mirror ✓ CUT	\$50.00	✓
10	Foot Rest & Mount ✓ BT	\$80.00	✓
11	Gear Shifter ✓ BT	\$40.00	✓
12	Brake Pedal ✓ CUT	\$40.00	✓
13	Left Engine Cover/Gasket ✓ CUT	\$100.00	✓
14	Front Wheel Shaft/Nut ✗ NN	\$40.00	✗
15	Fork Clamp/Stem/Steering Cone ✓ BT	\$180.00	✓
16	Fork ✓ BT	\$250.00	✓
17	Towing	\$50.00	40
18	Labour (Alightment Check)	\$200.00	100
19	Labour	\$1,000.00	500
	Total:	\$3,270.00	

Yours faithfully

Foo Meng Fong Rodney
Director
+65 9177 7178

1980
-10%: 1782
640
Total: 2422
3 Days
Part by part
After repair photos