

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB22000373/BEA3Q2**Date:** 20/07/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01

Claimant Vehicle No : SKQ129T **Insured Vehicle No :** SLW2573L

Date of Loss: 05/01/2022 Nature of Claim: TP Claim No: MFL2022D0000249

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKQ129T**

Make & Model: MAZDA 6, 2.0 4-DOOR SEDAN 2.0L SP.6EAT (A) Engine No: PY20421210

Reg. Date: 12/11/2014 (Man. Year: 2014) Chassis No: JM6GJ1031F0141368

Colour: White Odometer: 267240 km

Engine Capacity: 2488 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/55 R17 Rear Tyre Size: 255/55 R17

Front Left Side: Dunlop 5 mm Rear Left Side: Dunlop 5 mm

Front Right Side: Dunlop 5 mm Rear Right Side: Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,981.52	2,263.52	5,718.00	71.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,600.00	1,360.00	2,240.00	62.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,581.52	3,623.52	7,958.00	68.71
Approved Total (Overridden) (S\$)		2,850.00		
(S\$)	11,581.52	2,850.00	8,731.52	75.39
+ GST 7.00/7.00% (S\$)	810.71	199.50	611.21	75.39
Nett Amount (S\$)	12,392.23	3,049.50	9,342.73	75.39
+ Car Rental (11.0 x S\$180.00/day) (S\$)		1,980.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,036.95		
Global Sum Settlement (S\$)		5,030.00		

INSPECTION

Date of Assignment: 11/01/2022

Date Inspected: 11/01/2022 Inspected At:

Team Autopro Pte Ltd (sin Ming) (HQ)
160 SIN MING DRIVE, #01-14 SIN MING
AUTOCITY
Singapore 575722

Estimated Period of Repair: 7.0 days

Adjuster: Lim Teow Guan**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Mar 2022)

Parts: 143 MAZDA 6 2.0 4-DOOR SEDAN 2.0L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKQ129T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Dented	1,692.30 FL	*1,160.00 FL
2	1		*FRONT DOOR BLACK TAPE	Necessary	106.00 FL	*42.00 FL
3	1		*FRONT DOOR OUTER HANDLE W/SENSOR	Not Necessary	409.50 FL	*- FL
4	1		*FRONT DOOR WEATHERSTRIP	Not Necessary	182.10 FL	*- FL
5	1		*FRONT DOOR REGULATOR	Not Necessary	652.90 FL	*- FL
6	1		*FRONT DOOR REGULATOR MOTOR	Not Necessary	348.00 FL	*- FL
7	1		*FRONT DOOR INNER LOCK	Broken	328.90 FL	*275.40 FL
8	1		*FRONT DOOR LOCK STRIKER	Not Necessary	86.50 FL	*- FL
9	1		*FRONT DOOR CHECKER ARM	Not Necessary	102.80 FL	*- FL
10	1		*FRONT DOOR TRIMBOARD	Not Necessary	696.90 FL	*- FL
11	1		*FRONT DOOR FRAME RUBBER	Not Necessary	106.90 FL	*- FL
12	1		*SIDE MIRROR ASSY RH	Not Necessary	967.00 FL	*- FL
13	1		*REAR DOOR RH	Dented	1,585.00 FL	*1,160.00 FL
14	1		*REAR DOOR BLACK TAPE	Necessary	106.00 FL	*42.00 FL
15	1		*REAR DOOR WEATHERSTRIP	Not Necessary	142.10 FL	*- FL
16	1		*DOOR CENTRE PILLAR RH	Not Necessary	872.00 FL	*- FL
17	1		*ROCKER PANEL RH	Not Necessary	867.00 FL	*- FL
18	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
19	1		*FRONT DOOR SEALANT	Necessary	100.00 FS	*30.00 FS
20	1		*FRONT DOOR TRIMBOARD CLIPS	Necessary	50.00 FS	*30.00 FS
21	1		*REAR DOOR SEALANT	Necessary	100.00 FS	*30.00 FS
22	1		*REAR DOOR TRIMBOARD CLIPS	Necessary	50.00 FS	*30.00 FS
23	1		*DOOR CENTRE PILLAR SEALANT	Not Necessary	100.00 FS	*- FS
24	1		*ROCKER PANEL SEALANT	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,831.90	2,799.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,850.38	535.88

Total Parts (\$\$)	7,981.52	2,263.52
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R FRONT DOOR COMPONENT	New	150.00	80.00
2	R&R REAR DOOR COMPONENT	New	150.00	80.00
3	CHECK WIRING	New	100.00	0.00
4	DIAGNOSTIC RESET FAULT CODE	New	300.00	0.00
5	UPHOLSTERY	New	300.00	0.00
6	PANEL BEATING	New	1,200.00	800.00
7	RUST PROOFING	New	200.00	0.00
8	SPRAY PAINTING	New	1,200.00	400.00
Gross Labour Cost (\$)			3,600.00	1,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >