

# Lian Her Motor Works

BLK 5034 #01-337 Ang Mo Kio Industrial Pk 2 Singapore 569537  
Tel : 64817221

Fax : 64816131

AIG Asia Pacific Insurance Singapore Pte Ltd  
78 Shenton Way #07-16  
AIG Building  
Singapore 079120

Vehicle No : SJY 3365 C  
Make/Model : Honda Vezel 1.5 X A  
Year : 2020

*Not Withheld*  
*Repair After Paint*  
*11 Pay @ 3300p*  
*3 days*

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

## Estimate Cost Of Repair

1 pc	Rear tail-gate assy	953	
1 pc	Rear tail-gate glass moulding		\$1,170.30 ✓
1 pc	Rear tail-gate emblem " H "		\$105.20 ✓
1 pc	Rear tail-gate emblem : Vezel "		\$45.10 X
1 pc	Rear tail-gate outer garnish		\$50.20 ✓
1 pc	Rear tail-gate inner lock		\$205.70 X
1 pc	Rear tail-gate inner lock sensor		\$285.60 ✓
1 pc	Rear tail-gate inner trim board	295	\$225.10 ✓
1 pc	Rear o/s tail-gate lamp component		\$406.10 * ✓
1 pc	Rear o/s fender inner trim board		\$476.10 X
1 pc	Rear boot rubber		\$487.10 X
1 pc	Rear end panel		\$225.80 ✓
1 pc	Rear end panel inner garnish		\$455.10 X
1 pc	Rear bumper	762.70	\$185.90 ✓
1 pc	Rear o/s side bumper		\$855.60 ✓
2 pcs	Rear bumper side retainer		\$335.60 X
1 pc	Rear o/s bumper reflector		\$90.20 X
1 pc	Rear bumper lower garnish		\$155.20 X
1 pc	Rear exhaust silencer		\$175.20 X
1 pc	Rear spare tyre cover board		\$975.10 X
			\$205.10 X
			\$7,115.30
			Less 20 %
			\$1,423.06
			\$5,692.24

## S Nett

1 pc	Rear tail-gate glass sealant
1 pc	Rear reverse sensor
20 pcs	Rear bumper clip
1 pc	Rear no plate

### LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$2.00	\$40.00 ✓
	\$200.00 ✓
	\$40.00 ✓
	\$30.00 X
	\$310.00

balance c/f \$6,002.24

Tech Invs to  
Weekend (\$

TOTAL

REF: *716 / 2201121*

SJY 3365 C

Labour Charges

	balance b/f	\$6,002.24
Remove/renew the above parts including knocking, welding & cutting.	\$1,200.00	<i>500/</i>
To putty and spray paint	\$1,000.00	<i>600/</i>
Check & reconnect wiring.	\$45.00	<i>15/</i>
To respray anti-rust proofing treatment	\$100.00	<i>30/</i>
Remove/refit rear windscreen to facilitate repair	\$120.00	<i>✓</i>
Remove/refit rear tail-gate mechanism to new door.	\$100.00	<i>60/</i>
Remove/renew rear exhaust silencer.	<i>~</i> \$120.00	<i>X</i>
Remove/refit rear boot upholstery to facilitate repair.	\$100.00	<i>50/</i>
Total		<u><u>\$8,787.24</u></u>