

ASS. REC. BY:

REP:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLE 429D. Yr Regn: 2016 / July.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi S3 C.C. 1984

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 48252 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZZ8V361098251

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/35R19.

R: 245/35R19.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 14/01/22

*Survey held at Premium.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP AIG</u>
	<u>MV :</u>
	<u>PV :</u>
	<u>Nett :</u>

Date/Time, File Pass to?

☐ : Preli. Report

1) _____

☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

Report Format: _____

Loop 200 / LEJ: G

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Insp (\$ _____)

☐ : Weekend (\$ _____)

3 + RS \$

Photos

Others

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0032/2021/JT
DATE : 12-Jan-22
WIP : 63180

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 14/1/22
YOUR INSURED VEH NO : SKZ 2932 E

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING


SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS MARJORY YEOH
ADDRESS : 17 BALMEG HILL
#05-35
SINGAPORE 119919
TELEPHONE : HP +65 97461978
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100473347-05
VEHICLE NO : **SLE 429 D**
MODEL CODE : AUDI S3 SEDAN 2.0 TFSI
MODEL YEAR : 4/7/2016
ENGINE NO : CJX 117973
CHASSIS NO : WAUZZZ8V3G1098251
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 11-Jan-22
PLACE OF ACCIDENT : ENTRANCE OF WESTBAY CONDO
AT WEST COAST CRESCENT

PREMIUM AUTOMOBILES



85 ORCHARD 1, SINGAPORE 238699

TEL 63662323 FAX 68411183

EMAIL: INFO@PREMIUMAUTO.COM.SG CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLE 429 D

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION.	S/N \$ 280.00	✓ ✓
2	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHT, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$ 1,400.00	✓ ✓
3	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG, ETC.	S/N \$ 1,400.00	✓ ✓
4	TO RENEW REAR WINDSCREEN AND RHS 1/4 GLASS TO FACILITATE RENEWAL OF LHS REAR FENDER.	S/N \$ 600.00	✓ ✓
5	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND RHS 1/4 GLASS.	S/N \$ 400.00	✓ X NN
6	TO CARRY OUT WATER SEEPAGE TEST ON REAR WINDSCREEN AND 1/4 GLASS.	S/N \$ 200.00 150.	✓
TOTAL LABOUR CHARGES		: \$ 4,280.00	

[Handwritten signature]

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NOVA KHAN@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLE 429 D

SURVEYOR'S S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO DISMANTLE AND RENEW REAR BUMPER. CUT OUT AND WELD RHS REAR FENDER AND REAR END PANELLING. RE-ORGANIZE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 7,000.00	3000 ✓ H.S.
8	TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS SILL PANEL, ROOF CHANNEL, DOOR ENTRANCES, DRAIN CHANNEL, SPARE WHEEL HOUSING AND REAR END PANELLING	\$ 5,500.00	4.5 x 550 = 2475 ✓ H.S.
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 16,972.00	

SUB TOTAL SPARE PARTS \$ 23,925.00

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLE 429 D

RTS & PRICES

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>Distorted</i>	1	\$ 2,778.00 ✓	2,222.40
2	REAR BUMPER FIXING PARTS <i>New</i>	1	\$ 193.00 +	
3	REAR BUMPER GUIDE SECTION - LH / RH <i>7 RH DAMAGED</i>	2	\$ 32.00 ✓	12.64
4	REAR BUMPER LOCKING MECHANISM <i>new</i>	2	\$ 59.00 +	
5	REAR BUMPER SPOILER <i>at</i>	1	\$ 2,108.00 ✓	1,686.40
6	REAR LIGHT REFLECTOR - RH <i>crackd</i>	1	\$ 41.00 ✓	32.56
7	TAIL LIGHT - RH <i>new</i>	1	\$ 877.00 +	
8	TAIL LIGHT TRIM - RH <i>new</i>	1	\$ 30.00 +	
9	REAR BUMPER REINFORCEMENT BEAM <i>?</i>	1	\$ 603.00 X	
10	REAR BUMPER BRACKET - LH / RH <i>new</i>	2	\$ 26.00 +	
11	REAR BUMPER GUIDE SECTION - RH <i>Cracked</i>	1	\$ 67.00 ✓	52.96
12	REAR PARKING AID SENSOR - INNER / OUTER <i>OUTER DAMAGED</i>	2	TBC 264.70 ✓	211.76
13	REAR PARKING AID SENSOR SEAL RING <i>new</i> NEC	4	\$ 9.00 ✓	7.04
14	REAR BUMPER WIRING SET <i>new</i>	1	\$ 515.00 +	
15	C PILLAR - RH <i>Regr</i> BUC	1	\$ 4,140.00 ✓	3,312.00
16	REAR WINDSCREEN	1	\$ 814.00 ✓	651.20
17	QUARTER WINDOW <i>new</i> NEC	1	\$ 570.00 ✓	455.60
18	PRIMER	2	\$ 40.00 ✓	31.52
19	REAR END PANEL <i>?</i>	1	\$ 360.00 X	
20	REAR END PANEL REINFORCEMENT <i>?</i>	1	\$ 733.00 X	
SUB TOTAL SPARE PARTS			\$ 13,995.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLE429-D

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR END PANEL CONNECTING PLATE - LH / RH	2	\$ 290.00	
22	REAR VENT TRIM	1	\$ 68.00	
23	REAR WHEEL HOUSING LINER	1	\$ 240.00	
24	REAR WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 89.00	
25	EXHAUST TAIL PIPE TRIM - RH	1	\$ 143.00	
26	STONE CHIP	S/N	\$ 180.00	
27	ARYLIC SEALANT	S/N	\$ 180.00	
28	CAVITY WAX	S/N	\$ 140.00	
29	METAL FILLER POWDER	S/N	\$ 280.00	
30	1/4 GLASS SEALANT	S/N	\$ 100.00	
31	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	
32	SUNDRIES	\$	400.00	
TOTAL SPARE PARTS			\$ 16,305.00	
TOTAL LABOUR CHARGES			\$ 16,972.00	
GRAND TOTAL			\$ 33,277.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

17.92



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adnan Ly*
 SURVEYED DATE : *14/01/22*
 AUTHORISED DATE :
 EXCESS COST :
 LIABILITY :
 REMARKS : *Not Authorised, 03 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
 AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
 LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
 REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
 FOR INSPECTION OF VEHICLE, PLEASE REFER TO
 MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
 APPOINTMENT.

YOURS FAITHFULLY,
 PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
 BODY REPAIR MANAGER

ALLAN WU
 CLAIMS CONSULTANT

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

Asher.

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/TP/0032/2021/JT

17-Feb-22

CHANG

1 of 1

SLE 429 D

AUDI S3 SEDAN 2.0 TFSI

Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	TO CUT OUT AND WELD RHS REAR FENDER CONNECTING PLATE.	\$ 1,400.00	500 ✓
2	TO RESPRAY RHS REAR CONNECTING PLATE.	\$ 1,400.00	550 ✓
<u>Parts</u>			
1	CONNECTING PLATE - RH REAR <i>Buckled</i>	\$ 109.00	✓ 86.80
GRAND TOTAL		\$ 2,909.00	

For Premium Automobiles Pte Ltd



Authorised Signature

Adrian Ling
H.S.

Add 11 Days for the replacement
of rear fender and connecting plate
total number of days accorded
= 3 + 11 = 14 days H.S.