



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:CYNTHIA

Ref: CC4/ASM22000384/Apa3q2
Date: 17/03/2022
Code: ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 4633S	Veh. Inspected	SMK 7559Y
Policy No.	P2465703	Coverage (\$)	0.00
Claim No.	S2M03QR0	Excess (\$)	0.00
Assign From		Assign Date	11/01/2022

2. Vehicle Particulars & Condition

Make & Model	MAZDA 2	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JM6DJ2HAA01300369	Colour	BLACK
Odometer	30184 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/65 R15	DUNLOP	6 mm
L/H Front Tyre	185/65 R15	DUNLOP	6 mm
R/H Rear Tyre	185/65 R15	DUNLOP	6 mm
L/H Rear Tyre	185/65 R15	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/01/2022	Inspection Date	12/01/2022
Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**