

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL 6366 2323 FAX 6841 1183

EMAIL: NORA@KHAI@PREMIUMAUTO.COM.SG CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0015/2021/JT
DATE : 7-Jan-22
WIP : 62390

Veron.

\$11129.36

04 Days.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 10/1/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838


OWNER'S NAME : MR LEE KAY CHAI
ADDRESS : 2 SPRINGLEAF RISE
SINGAPORE 787982
TELEPHONE : HP +65 96758681
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900045219-02
VEHICLE NO : SFD 228 T
MODEL CODE : AUDI RS5 COUPE 2.9 TFSI
MODEL YEAR : 21/3/2019
ENGINE NO : DEC 014653
CHASSIS NO : WAUZZZF59KA903428
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 6-Jan-22
PLACE OF ACCIDENT : THE JUNCTION OF SENOKO
DRIVE & ATTAP VALLEY ROAD

PREMIUM AUTOMOBILES

55 UBI ROAD 1 SINGAPORE 408699


TEL: 6366 2323 FAX: 6341 1181

EMAIL: NORA.KHAIR@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFD 228 T

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	S/N \$ 480.00	✓ ✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 450.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,700.00	500 ✓
4	TO RESPRAY FRONT BUMPER AND BONNET.	\$ 2,500.00	1100 ✓
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 6,322.00	



PREMIUM AUTOMOBILES

55 UBI ROAD 1 SINGAPORE 478609
TEL: 6366 2123 FAX: 6341 1183
E-MAIL: NURA_HAT@PREMIUMAUTOS.COM SG / CLAIMS@PREMIUMAUTOS.COM SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFD 228 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>del</i>	1 S	6,264.00	✓ 5011.20
2	FRONT BUMPER SECURING STRIP - LH / RH <i>new</i>	2 S	90.00	X
3	FRONT BUMPER AIR GUIDE - LH / RH <i>new</i>	2 S	334.00	✓
4	FRONT BUMPER SPOILER - UPPER <i>new</i>	1 S	613.00	✓
5	FRONT BUMPER GRILLE - CENTER <i>new</i>	1 S	722.00	✓
6	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>new</i>	1 S	350.00	✓
7	FRONT BUMPER SPOILER - CENTER <i>new</i>	1 S	708.00	✓
8	FRONT BUMPER SPOILER - LOWER <i>new</i>	1 S	856.00	✓
9	FRONT BUMPER SPOILER - LH / RH <i>new</i>	2 S	1,352.00	✓
10	FRONT BUMPER AIR GUIDE GRILLE - LH <i>new</i>	1 S	736.00	✓
11	RADIATOR AIR GUIDE - LH <i>new</i>	1 S	75.00	✓
12	FRONT BUMPER AIR GUIDE - LH <i>new</i>	1 S	226.00	✓
13	RADIATOR GRILLE <i>cracked</i>	1 S	3,508.00	✓ 2806.40
14	FRONT PARKING AID SENSOR SUPPORT - LH / RH <i>new</i>	2 S	178.00	✓
15	"RSS" EMBLEM <i>new</i>	1 S	128.00	✓ 102.40
16	FRONT BUMPER LOWER COVER <i>new</i> tor	1 S	213.00	+ 170.40
17	RADIATOR GRILLE - UPPER <i>new</i>	1 S	253.00	✓
18	LICENCE PLATE HOLDER <i>cracked</i>	1 S	621.00	✓ 496.80
19	FRONT BUMPER FOAM FILLER PIECE <i>new</i>	1 S	303.00	✓
20	FRONT BUMPER REINFORCEMENT BEAM <i>new</i>	1 S	845.00	✓
SUB TOTAL SPARE PARTS			\$ 18,375.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT

PREMIUM AUTOMOBILES




35 LEE ROAD 1, SINGAPORE 408679
 TEL: 6754 2224 FAX: 6741 1193
 EMAIL: WORK@KHATIBPREMIUMAUTOMOBILES.COM

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFD 228 T

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NEIT		
21	FRONT BUMPER GUIDE SECTION - LH <i>ALC</i>	1	\$	67.00 +	
22	FRONT BUMPER TOP COVER } <i>torn</i>	1	\$	242.00 +	193.60
23	"CAUTION" STICKER <i>nec</i>	1	\$	14.00 +	10.88
24	AIR COND STICKER <i>nec</i>	1	\$	8.00 +	5.68
25	FRONT BUMPER LOCK CARRIER BRACKET <i>nec</i> <i>Not nec</i>	1	\$	137.00	X
26	FRONT BUMPER SUPPORT - LH / RH <i>ALC</i>	2	\$	58.00 +	
27	FRONT POP RIVET <i>Not nec</i>	4	\$	4.00	X
28	HORN - LH } <i>ALC</i>	1	\$	201.00 +	
29	HORN SUPPORT - LH	1	\$	50.00 +	
30	FRONT PARKING AID SENSOR - INNER / OUTER <i>ALC</i>	2		TBC	X
31	FRONT PAKING AID SENSOR SEAL RING <i>ALC</i>	4	\$	9.00 +	
32	BONNET <i>Repair</i>	1	\$	3,312.00 +	
33	BONNET IMPACT PROTECTION - CENTER / LH / RH <i>ALC</i>	3	\$	84.00 +	
34	BONNET STRIKER - LH } <i>ALC</i>	1	\$	50.00 +	
35	BONNET LOCK	1	\$	214.00 +	
36	HEADLIGHT - LH	1	\$	7,902.00 +	
37	LIFT CYLINDER - LH	1	\$	198.00 +	
38	LIFT CYLINDER CORRUGATED PIPE } <i>ALC</i>	1	\$	86.00 +	
39	BONNET TRIM RETAINER - LH	1	\$	49.00 +	
40	BONNET TRIM - LH	1	\$	402.00 +	
41	FRONT NO PLATE <i>Dented</i>	S/N	\$	60.00 +	60
42	SUNDRIES <i>Not nec</i>		\$	400.00	X
TOTAL SPARE PARTS		:	\$	31,922.00	
TOTAL LABOUR CHARGES		:	\$	6,322.00	
GRAND TOTAL		:	\$	38,244.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) - APPROVED, REMARKS (X) - NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD, SINGAPORE 408699
TEL 6766 2323 FAX 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Adrian Lj
10/01/22

Not Authorised, out pays
H.G.

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: