

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Syed-Yusoff, Saliha

Date: 12 Jan 2022

Preliminary Advice

Vehicle No	: SFD228T	Accident Date	: 06/01/2022
Make	: AUDI RS5 COUPE	Policy No.	:
Assignment Date	: 11/01/2022	Excess	: S\$0.00
Date of Inspection	: 10/1/2022	Est. Duration of Repair	: 4
Inspection At	: PREMIUM AUTOMOBILES PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	38,244.00
Revised Amount	:S\$	12,853.00
Check Items (Estimated)	:S\$	631.00
Total	:S\$	13,484.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	310,000.00
COE / PARF Rebate	:S\$	113,941.00
Salvage Value	:S\$	
Margin for Repair	:S\$	196,059.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : . Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .