



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/0015/2021/JT  
DATE : 7-Jan-22  
WIP : 62390

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 10/1/22**

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY  
#07-16 AIG BUILDING  
SINGAPORE 079120  
Attn: Motor Claims Dept  
**Tel: 6880 4602 - Fax: 6880 4838**

**OWNER'S NAME** : MR LEE KAY CHAI  
**ADDRESS** : 2 SPRINGLEAF RISE  
SINGAPORE 787982  
**TELEPHONE** : HP +65 96758681  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 1900045219-02  
**VEHICLE NO** : **SFD 228 T**  
**MODEL CODE** : AUDI RS5 COUPE 2.9 TFSI  
**MODEL YEAR** : 21/3/2019  
**ENGINE NO** : DEC 014653  
**CHASSIS NO** : WAUZZZF59KA903428  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 6-Jan-22  
**PLACE OF ACCIDENT** : THE JUNCTION OF SENOKO  
DRIVE & ATTAP VALLEY ROAD


55 UBI ROAD 1, SINGAPORE 408699  
 TEL: 6366 2323 FAX: 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

55 UBI ROAD 1, SINGAPORE 408699  
 TEL: 6366 2323 FAX: 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFD 228 T**

SURVEYOR'S RECOMMENDATIONS	S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
	1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	S/N \$ 480.00	✓
	2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 450.00	X
	3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,700.00	500
	4	TO RESPRAY FRONT BUMPER AND BONNET.	\$ 2,500.00	1100
	5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
<b>TOTAL LABOUR CHARGES</b>			<b>: \$ 6,322.00</b>	

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFD 228 T

ESTIMATED LABOUR CHARGES FOR

PARTS & PRICES

ESTIMATED

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>del</i>	1	\$ 6,264.00	✓
2	FRONT BUMPER SECURING STRIP - LH / RH ?	2	\$ 90.00	?
3	FRONT BUMPER AIR GUIDE - LH / RH <i>new</i>	2	\$ 334.00	+
4	FRONT BUMPER SPOILER - UPPER <i>new</i>	1	\$ 613.00	+
5	FRONT BUMPER GRILLE - CENTER <i>new</i>	1	\$ 722.00	+
6	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>new</i>	1	\$ 350.00	+
7	FRONT BUMPER SPOILER - CENTER <i>new</i>	1	\$ 708.00	+
8	FRONT BUMPER SPOILER - LOWER <i>new</i>	1	\$ 856.00	+
9	FRONT BUMPER SPOILER - LH / RH	2	\$ 1,352.00	+
10	FRONT BUMPER AIR GUIDE GRILLE - LH <i>new</i>	1	\$ 736.00	+
11	RADIATOR AIR GUIDE - LH <i>new</i>	1	\$ 75.00	+
12	FRONT BUMPER AIR GUIDE - LH <i>new</i>	1	\$ 226.00	+
13	RADIATOR GRILLE <i>cracked</i>	1	\$ 3,508.00	✓
14	FRONT PARKING AID SENSOR SUPPORT - LH / RH <i>new</i>	2	\$ 178.00	+
15	"RSS" EMBLEM <i>new</i>	1	\$ 128.00	✓
16	FRONT BUMPER LOWER COVER <i>new</i>	1	\$ 213.00	+
17	RADIATOR GRILLE - UPPER <i>new</i>	1	\$ 253.00	+
18	LICENCE PLATE HOLDER <i>cracked</i>	1	\$ 621.00	✓
19	FRONT BUMPER FOAM FILLER PIECE <i>new</i>	1	\$ 303.00	+
20	FRONT BUMPER REINFORCEMENT BEAM <i>new</i>	1	\$ 845.00	+
<b>SUB TOTAL SPARE PARTS</b>			<b>\$ 18,375.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
 TEL: 6366 2323 FAX: 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG /RELAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFD 228 T**

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT BUMPER GUIDE SECTION - LH <i>new</i>	1	\$ 67.00	+
22	FRONT BUMPER TOP COVER <i>new</i>	1	\$ 242.00	+
23	"CAUTION" STICKER <i>new</i>	1	\$ 14.00	+
24	AIR COND STICKER	1	\$ 8.00	+
25	FRONT BUMPER LOCK CARRIER BRACKET <i>new ?</i>	1	\$ 137.00	?
26	FRONT BUMPER SUPPORT - LH / RH <i>new</i>	2	\$ 58.00	+
27	FRONT POP RIVET <i>?</i>	4	\$ 4.00	?
28	HORN - LH <i>new</i>	1	\$ 201.00	+
29	HORN SUPPORT - LH	1	\$ 50.00	+
30	FRONT PARKING AID SENSOR - INNER / OUTER <i>new</i>	2	TBC	+
31	FRONT PAKING AID SENSOR SEAL RING <i>new</i>	4	\$ 9.00	+
32	BONNET <i>Repair</i>	1	\$ 3,312.00	+
33	BONNET IMPACT PROTECTION - CENTER / LH / RH <i>new</i>	3	\$ 84.00	+
34	BONNET STRIKER - LH <i>new</i>	1	\$ 50.00	+
35	BONNET LOCK <i>new</i>	1	\$ 214.00	+
36	HEADLIGHT - LH	1	\$ 7,902.00	+
37	LIFT CYLINDER - LH	1	\$ 198.00	+
38	LIFT CYLINDER CORRUGATED PIPE <i>new</i>	1	\$ 86.00	+
39	BONNET TRIM RETAINER - LH <i>new</i>	1	\$ 49.00	+
40	BONNET TRIM - LH	1	\$ 402.00	+
41	FRONT NO PLATE <i>Dented</i>	S/N	\$ 60.00	+
42	SUNDRIES <i>?</i>		\$ 400.00	?
<b>TOTAL SPARE PARTS</b>		:	<b>\$ 31,922.00</b>	
<b>TOTAL LABOUR CHARGES</b>		:	<b>\$ 6,322.00</b>	
<b>GRAND TOTAL</b>		:	<b>\$ 38,244.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
TEL: 6366 2323 FAX: 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adnan Lj*  
SURVEYED DATE : *10/01/22*  
AUTHORISED DATE :  
EXCESS COST :  
LIABILITY :  
REMARKS : *Not Authorised, 04 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: