



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0015/2021/JT
DATE : 7-Jan-22
WIP : 62390

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 10/1/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

4 days - ok - Johnny Boo

14-Mar-22

OWNER'S NAME : MR LEE KAY CHAI
ADDRESS : 2 SPRINGLEAF RISE
SINGAPORE 787982
TELEPHONE : HP +65 96758681
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900045219-02
VEHICLE NO : **SFD 228 T**
MODEL CODE : AUDI RS5 COUPE 2.9 TFSI
MODEL YEAR : 21/3/2019
ENGINE NO : DEC 014653
CHASSIS NO : WAUZZZF59KA903428
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 6-Jan-22
PLACE OF ACCIDENT : THE JUNCTION OF SENOKO
DRIVE & ATTAP VALLEY ROAD

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFD 228 T

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$ 480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	450.00	
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND LHS HEADLIGHT. RE-ORGANZIE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,700.00	\$ 500.00
4	TO RESPRAY FRONT BUMPER AND BONNET.	\$	2,500.00	\$ 1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 6,322.00	\$ 2,272.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFD 228 T

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS		
1	FRONT BUMPER	1	\$ 6,264.00	\$	5,011.20	
2	FRONT BUMPER SECURING STRIP - LH / RH	2	\$ 90.00			
3	FRONT BUMPER AIR GUIDE - LH / RH	2	\$ 334.00			
4	FRONT BUMPER SPOILER - UPPER	1	\$ 613.00			
5	FRONT BUMPER GRILLE - CENTER	1	\$ 722.00			
6	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1	\$ 350.00			
7	FRONT BUMPER SPOILER - CENTER	1	\$ 708.00			
8	FRONT BUMPER SPOILER - LOWER	1	\$ 856.00			
9	FRONT BUMPER SPOILER - LH / RH	2	\$ 1,352.00			
10	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 736.00			
11	RADIATOR AIR GUIDE - LH	1	\$ 75.00			
12	FRONT BUMPER AIR GUIDE - LH	1	\$ 226.00			
13	RADIATOR GRILLE	1	\$ 3,508.00	\$	2,806.40	
14	FRONT PARKING AID SENSOR SUPPORT - LH / RH	2	\$ 178.00			
15	"RS5" EMBLEM	1	\$ 128.00	\$	102.40	
16	FRONT BUMPER LOWER COVER	1	\$ 213.00	\$	170.40	
17	RADIATOR GRILLE - UPPER	1	\$ 253.00			
18	LICENCE PLATE HOLDER	1	\$ 621.00	\$	496.80	
19	FRONT BUMPER FOAM FILLER PIECE	1	\$ 303.00			
20	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 845.00			
SUB TOTAL SPARE PARTS		:	\$ 18,375.00	\$	8,587.20	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFD 228 T

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		
			S/NETT	REMARKS	
					8,587.20
		<i>C/F</i>		\$	
21	FRONT BUMPER GUIDE SECTION - LH	1	\$	67.00	
22	FRONT BUMPER TOP COVER	1	\$	242.00	\$ 193.60
23	"CAUTION" STICKER	1	\$	14.00	\$ 10.88
24	AIR COND STICKER	1	\$	8.00	\$ 5.68
25	FRONT BUMPER LOCK CARRIER BRACKET	1	\$	137.00	
26	FRONT BUMPER SUPPORT - LH / RH	2	\$	58.00	
27	FRONT POP RIVET	4	\$	4.00	
28	HORN - LH	1	\$	201.00	
29	HORN SUPPORT - LH	1	\$	50.00	
30	FRONT PARKING AID SENSOR - INNER / OUTER	2		TBC	
31	FRONT PAKING AID SENSOR SEAL RING	4	\$	9.00	
32	BONNET	1	\$	3,312.00	
33	BONNET IMPACT PROTECTION - CENTER / LH / RH	3	\$	84.00	
34	BONNET STRIKER - LH	1	\$	50.00	
35	BONNET LOCK	1	\$	214.00	
36	HEADLIGHT - LH	1	\$	7,902.00	
37	LIFT CYLINDER - LH	1	\$	198.00	
38	LIFT CYLINDER CORRUGATED PIPE	1	\$	86.00	
39	BONNET TRIM RETAINER - LH	1	\$	49.00	
40	BONNET TRIM - LH	1	\$	402.00	
41	FRONT NO PLATE	S/N	\$	60.00	\$ 60.00
42	SUNDRIES		\$	400.00	
TOTAL SPARE PARTS		:	\$	31,922.00	\$ 8,857.36
TOTAL LABOUR CHARGES		:	\$	6,322.00	\$ 2,272.00
GRAND TOTAL		:	\$	38,244.00	\$ 11,129.36

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-25/02/22



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT