

Car 20

24/1/22

wip: 62390

Kram / Veron

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL 6366 2323 FAX 6341 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Asst- Adrian



- 4 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFD 228 T

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>rehab</i>	1	\$ 6,264.00	✓
2	FRONT BUMPER SECURING STRIP - LH / RH ?	2	\$ 90.00	?
3	FRONT BUMPER AIR GUIDE - LH / RH <i>neu</i>	2	\$ 334.00	+
4	FRONT BUMPER SPOILER - UPPER <i>neu</i>	1	\$ 613.00	✓
5	FRONT BUMPER GRILLE - CENTER <i>neu</i>	1	\$ 722.00	+
6	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>neu</i>	1	\$ 350.00	+
7	FRONT BUMPER SPOILER - CENTER <i>neu</i>	1	\$ 708.00	+
8	FRONT BUMPER SPOILER - LOWER <i>neu</i>	1	\$ 856.00	✓
9	FRONT BUMPER SPOILER - LH / RH <i>neu</i>	2	\$ 1,352.00	✓
10	FRONT BUMPER AIR GUIDE GRILLE - LH <i>neu</i>	1	\$ 736.00	+
11	RADIATOR AIR GUIDE - LH <i>neu</i>	1	\$ 75.00	+
12	FRONT BUMPER AIR GUIDE - LH <i>neu</i>	1	\$ 226.00	+
13	RADIATOR GRILLE <i>crushed</i>	1	\$ 3,508.00	✓
14	FRONT PARKING AID SENSOR SUPPORT - LH / RH <i>neu</i>	2	\$ 178.00	+
15	ASS' EMBLEM <i>neu</i>	1	\$ 128.00	✓
16	FRONT BUMPER LOWER COVER <i>new torn</i>	1	\$ 213.00	✓ <i>sl.s.</i>
17	RADIATOR GRILLE - UPPER <i>neu</i>	1	\$ 253.00	+
18	LICENCE PLATE HOLDER <i>crushed</i>	1	\$ 621.00	✓
19	FRONT BUMPER FOAM FILLER PIECE <i>neu</i>	1	\$ 303.00	+
20	FRONT BUMPER REINFORCEMENT BEAM <i>neu</i>	1	\$ 845.00	+
SUB TOTAL SPARE PARTS			\$ 18,375.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

*Resmged
Adrian Lj
sl.s.*

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFD 228 T

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT BUMPER GUIDE SECTION - LH <i>ALC</i>	1	\$ 67.00	+
22	FRONT BUMPER TOP COVER <i>to be</i>	1	\$ 242.00	+
23	"CAUTION" STICKER <i>3 per</i>	1	\$ 14.00	+
24	AIR COND STICKER	1	\$ 8.00	+
25	FRONT BUMPER LOCK CARRIER BRACKET <i>ALC ?</i>	1	\$ 137.00	?
26	FRONT BUMPER SUPPORT - LH / RH <i>ALC</i>	2	\$ 58.00	+
27	FRONT POP RIVET ?	4	\$ 4.00	?
28	HORN - LH <i>3 per</i>	1	\$ 201.00	+
29	HORN SUPPORT - LH	1	\$ 50.00	+
30	FRONT PARKING AID SENSOR - INNER / OUTER <i>ALC</i>	2	TBC	+
31	FRONT PAKING AID SENSOR SEAL RING <i>ALC</i>	4	\$ 9.00	+
32	BONNET <i>Repair</i>	1	\$ 3,312.00	+
33	BONNET IMPACT PROTECTION - CENTER / LH / RH <i>ALC</i>	3	\$ 84.00	+
34	BONNET STRIKER - LH ?	1	\$ 50.00	+
35	BONNET LOCK <i>ALC</i>	1	\$ 214.00	+
36	HEADLIGHT - LH	1	\$ 7,902.00	+
37	LIFT CYLINDER - LH	1	\$ 198.00	+
38	LIFT CYLINDER CORRUGATED PIPE ?	1	\$ 86.00	+
39	BONNET TRIM RETAINER - LH <i>ALC</i>	1	\$ 49.00	+
40	BONNET TRIM - LH	1	\$ 402.00	+
41	FRONT NO PLATE <i>Dented</i>	S/N	\$ 60.00	+
42	SUNDRIES ?		\$ 400.00	?
TOTAL SPARE PARTS		:	\$ 31,922.00	
TOTAL LABOUR CHARGES		:	\$ 6,322.00	
GRAND TOTAL		:	\$ 38,244.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.