

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0016/2021/JT
DATE : 07-Jan-22
WIP : 62425

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 10/11/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian,

7 days - ok - Jy - 7 May 22

OWNER'S NAME : MR ANJALI GROVER SINGH
ADDRESS : 10 DRAYCOTT PARK
#10-08
SINGAPORE 259405
TELEPHONE : HP +65 97576236
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100507400-04
VEHICLE NO : **SLN 491 A**
MODEL CODE : AUDI A8L D4 3.0TFSI QU
MODEL YEAR : 20/04/2017
ENGINE NO : CRE 152029
CHASSIS NO : WAUZZZ4H2HN015984
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 05-Jan-22
PLACE OF ACCIDENT : BEFORE PATERSON ROAD
& ORCHARD ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLN 491 A

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	900.00	\$	300.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM, VACCUM AND REGAS.	S/N \$	2,000.00	\$	780.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDER, BONNET AND BOTH HEADLIGHTS, TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	7,200.00	\$	2,400.00
5	TO RESPRAY FRONT BUMPER, BONNET, HINGES AND BOTH FRONT FENDER.	\$	5,000.00	\$	1,200.00
6	TO CARRY OUT CALIBRATION FOR FRONT BUMPER RADAR SENSOR.	S/N \$	480.00		
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 16,252.00	\$	5,352.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLN 491 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 3,649.00	\$ 2,919.20
2	FRONT BUMPER FIXING PARTS	1	\$ 493.00	
3	FRONT BUMPER GRILLE	1	\$ 708.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER	1	\$ 262.00	
5	FRONT BUMPER SPOILER - LOWER	1	\$ 297.00	
6	FRONT WHEEL SPOILER OUTER - LH / RH	2	\$ 88.00	
7	FRONT WHEEL SPOILER INNER - LH / RH	2	\$ 74.00	
8	RADIATOR GRILLE	1	\$ 3,508.00	\$ 2,806.40
9	QUATTRO EMBLEM	1	\$ 106.00	\$ 84.80
10	FRONT BUMPER EMBLEM CLIP	2	\$ 15.00	\$ 11.36
11	EMBLEM COVER	1	\$ 61.00	\$ 48.16
12	EMBLEM COVER CAP	1	\$ 114.00	
13	RADIATOR GRILLE BRACKET	1	\$ 27.00	\$ 21.44
14	RADIATOR GRILLE REINFORCEMENT - LH / RH	2	\$ 98.00	\$ 38.80
15	FRONT PARKING AID SENSOR SUPPORT - LH / RH	2	\$ 96.00	
16	FRONT CAMERA	1	\$ 959.00	
17	FRONT CAMERA ADAPTER	1	\$ 416.00	
18	LICENCE PLATE HOLDER	1	\$ 459.00	\$ 367.20
19	FRONT BUMPER GRILLE OUTER - LH / RH	2	\$ 1,038.00	
20	FRONT BUMPER END CAP - RH	1	\$ 68.00	
SUB TOTAL SPARE PARTS		:	\$ 12,536.00	\$ 6,297.36

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLN 491 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
				\$ 6,297.36
21	FRONT BUMPER FOAM FILLER PIECE	1	\$ 127.00	\$ 101.20
22	FRONT BUMPER REINFORCEMENT COVER	1	\$ 98.00	\$ 78.00
23	FRONT BUMPER TRIM BRACKET - LH / RH	2	\$ 50.00	\$ 19.44
24	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 1,157.00	
25	FRONT BUMPER RETAINING BRACKET - LH / RH	2	\$ 50.00	
26	FRONT BUMPER GUIDE PIECE - LH / RH	2	\$ 106.00	
27	FRONT BUMPER TOP COVER	1	\$ 242.00	\$ 193.60
28	AIR COND STICKER	1	\$ 20.00	\$ 15.52
29	CAUTION STICKER	1	\$ 14.00	\$ 10.88
30	FRONT BUMPER PARKING AID SENSOR	4	TBC	
31	FORNT PARKING AID SENSOR SEAL RING	4	\$ 6.00	
32	FRONT BUMPER WIRING SET	1	\$ 676.00	
33	HORN - HIGH / LOW TONE	2	\$ 483.00	
34	HORN SUPPORT	1	\$ 91.00	\$ 72.72
35	BONNET	1	\$ 6,645.00	
36	BONNET ATTACHMENT PARTS	1	\$ 266.00	
37	BONNET CATCH HOOK	1	\$ 156.00	
38	BONNET HINGE - LH / RH	2	\$ 542.00	
39	BONNET SEAL	1	\$ 60.00	
40	BONNET LOCK BAR	2	\$ 240.00	
SUB TOTAL SPARE PARTS		:	\$ 11,029.00	\$ 6,788.72

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLN 491 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
				\$ 6,788.72
41	BONNET LOCK - LH / RH	2	\$ 457.00	
42	BONNET LOCK HOUSING - LH / RH	2	\$ 92.00	
43	BONNET LOCK SWITCH - LH / RH	2	\$ 148.00	
44	BONNET LOCK COVER	2	\$ 8.00	
45	BONNET BOWDEN CABLE - CENTER	1	\$ 58.00	
46	BONNET BOWDEN CABLE COVER	1	\$ 10.00	
47	RADIATOR CATCH HOOK	1	\$ 153.00	
48	TERMINAL SOCKET CABLE TIE	2	\$ 5.00	
49	FRONT FENDER SIDE COVER - LH / RH	2	\$ 30.00	
50	FRONT FENDER - LH / RH	2	\$ 3,684.00	
51	FRONT FENDER ATTACHMENT PARTS	1	\$ 287.00	
52	FRONT CONNECTING PIECE - LH / RH	2	\$ 486.00	
53	FRONT FENDER BRACE - LH / RH	2	\$ 1,700.00	
54	FRONT FENDER BRACKET - LH / RH	2	\$ 50.00	
55	FRONT FENDER BRACKET END - LH / RH	2	\$ 68.00	
56	FRONT WHEEL HOUSING LINER - LH / RH	2	\$ 592.00	
57	HEADLIGHT - LH / RH	2	\$ 26,162.00	\$ 10,464.80
58	LIFT CYLINDER - LH / RH	2	\$ 472.00	
59	LIFT CYLINDER HOSE	1	\$ 109.00	
60	LIFT CYLINDER SECURING BRACKET - LH / RH	2	\$ 376.00	
SUB TOTAL SPARE PARTS		:	\$ 34,947.00	\$ 17,253.52

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLN 491 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
				\$ 17,253.52
61	LOCK CARRIER	1	\$ 1,131.00	
62	LOCK CARRIER SUPPORT	1	\$ 741.00	
63	LOCK CARRIER SIDE MEMBER - LH / RH	2	\$ 392.00	
64	A/C CONDENSER	1	\$ 960.00	\$ 768.00
65	OUTSIDE TEMPERATURE SENSOR	1	\$ 59.00	
66	ADDITIONAL RADIATOR	1	\$ 1,134.00	
67	RADIATOR COOLANT - CENTER	1	\$ 1,355.00	
68	RADIATOR COOLANT	6	\$ 266.00	
69	RADIATOR AIR GUIDE - LH / RH	2	\$ 54.00	
70	RADIATOR AIR GUIDE - UPPER CENTER	1	\$ 42.00	
71	RADIATOR AIR GUIDE SEAL - LOWER	1	\$ 37.00	
72	FRONT NO PLATE	S/N	\$ 60.00	\$ 60.00
	SUPP - See attachment			\$ 68.56
73	SUNDRIES		\$ 400.00	\$ 99.92
TOTAL SPARE PARTS			\$ 65,143.00	\$ 18,250.00
TOTAL LABOUR CHARGES			\$ 16,252.00	\$ 5,352.00
GRAND TOTAL			\$ 81,395.00	\$ 23,602.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0016/2021/JT

25-Feb-22

CHANG

1 of 1

SLN 491 A

AUDI A8L D4 3.0 TFSI QU

Quantity	Description	Unit Price	Amount
Parts			
1	AIR INTAKE DUCT COVER	\$ 29.00	\$ 23.20
2	AIR INTAKE AIR DUCT	\$ 57.00	\$ 45.36
GRAND TOTAL		\$ 86.00	\$ 68.56

For Premium Automobiles Pte Ltd

 Authorised Signature

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT