

PREMIUM AUTOMOBILES



55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate-1

Veron.

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0016/2021/JT
25-Feb-22
CHANG
1 of 1
SLN 491 A
AUDI A8L D4 3.0 TFSI QU

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	AIR INTAKE DUCT COVER <i>behind</i>	\$ 29.00	<i>=</i>
2	AIR INTAKE AIR DUCT <i>under</i>	\$ 57.00	
GRAND TOTAL		\$ 86.00	

For Premium Automobiles Pte Ltd

Adrian Ling
H.P.S.




Authorised Signature

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM SG7 CLAIMS@PREMIUMAUTO.COM SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLN 491 A

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	S/N \$ 480.00 ✓	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 900.00 <u>250</u> ✓	\$300 sls.
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM, VACCUM AND REGAS.	S/N \$ 2,000.00 ✓	\$780 sls.
4	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDER, BONNET AND BOTH HEADLIGHTS, TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 7,200.00 ✓	240 (inclusive of removal of lock carrier)
5	TO RESPRAY FRONT BUMPER, BONNET, HINGES AND BOTH FRONT FENDER.	\$ 5,000.00 1200 ✓	
6	TO CARRY OUT CALIBRATION FOR FRONT BUMPER RADAR SENSOR.	S/N \$ 480.00 ?	
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>16,252.00</u>	

Resurvey of removal of lock carrier required

Car-in 9/2/12 wip: 62425

PREMIUM AUTOMOBILES

Kiam/



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

AIG - Adnan - 7 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLN 491 A

PARTS & PRICES				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER Distorted	1	S	3,649.00	✓
2	FRONT BUMPER FIXING PARTS New	1	S	493.00	+
3	FRONT BUMPER GRILLE New	1	S	708.00	+
4	FRONT BUMPER CLOSING ELEMENT - LOWER New	1	S	262.00	+
5	FRONT BUMPER SPOILER - LOWER New	1	S	297.00	+
6	FRONT WHEEL SPOILER OUTER - LH / RH 2 New	2	S	88.00	+
7	FRONT WHEEL SPOILER INNER - LH / RH	2	S	74.00	+
8	RADIATOR GRILLE Audi	1	S	3,508.00	✓
9	QUATTRO EMBLEM 2 New	1	S	106.00	✓
10	FRONT BUMPER EMBLEM CLIP	2	S	15.00	✓
11	EMBLEM COVER New	1	S	61.00	✓
12	EMBLEM COVER CAP ?	1	S	114.00	?
13	RADIATOR GRILLE BRACKET Audi	1	S	27.00	✓
14	RADIATOR GRILLE REINFORCEMENT - LH / RH 2 RH 2nd	2	S	98.00	49. fl.s.
15	FRONT PARKING AID SENSOR SUPPORT - LH / RH ?	2	S	96.00	?
16	FRONT CAMERA ?	1	S	959.00	?
17	FRONT CAMERA ADAPTER ?	1	S	416.00	?
18	LICENCE PLATE HOLDER Defect	1	S	459.00	✓
19	FRONT BUMPER GRILLE OUTER - LH / RH New	2	S	1,038.00	+
20	FRONT BUMPER END CAP - RH New	1	S	68.00	+
SUB TOTAL SPARE PARTS			:	\$	12,536.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6641 1183

EMAIL: NORA.KHAN@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLN 491 A

ITEMS & PRICES

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT BUMPER FOAM FILLER PIECE <i>could</i>	1	S 127.00	✓
22	FRONT BUMPER REINFORCEMENT COVER <i>could</i>	1	S 98.00	✓
23	FRONT BUMPER TRIM BRACKET - LH / RH <i>RH mtd</i>	2	S 50.00	✓
24	FRONT BUMPER REINFORCEMENT BEAM ?	1	S 1,157.00	?
25	FRONT BUMPER RETAINING BRACKET - LH / RH <i>new</i>	2	S 50.00	+
26	FRONT BUMPER GUIDE PIECE - LH / RH ?	2	S 106.00	?
27	FRONT BUMPER TOP COVER <i>could</i>	1	S 242.00	✓
28	AIR COND STICKER	1	S 20.00	✓
29	CAUTION STICKER <i>new</i>	1	S 14.00	✓
30	FRONT BUMPER PARKING AID SENSOR <i>new</i>	4	TBC	+
31	FORNT PARKING AID SENSOR SEAL RING <i>new</i>	4	S 6.00	+
32	FRONT BUMPER WIRING SET <i>new</i>	1	S 676.00	+
33	HORN - HIGH / LOW TONE <i>new</i>	2	S 483.00	X
34	HORN SUPPORT <i>new Bent</i>	1	S 91.00	✓
35	BONNET <i>new</i>	1	S 6,645.00	+
36	BONNET ATTACHMENT PARTS	1	S 266.00	+
37	BONNET CATCH HOOK	1	S 156.00	+
38	BONNET HINGE - LH / RH <i>new</i>	2	S 542.00	+
39	BONNET SEAL <i>new</i>	1	S 60.00	X
40	BONNET LOCK BAR	2	S 240.00	+
SUB TOTAL SPARE PARTS		:	\$ 11,029.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.