



55 UBI ROAD 1, SINGAPORE 408699

T.L: 6366 2323 FAX: 6841 1183

EMAIL: NURA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0023/2021/JT
DATE : 10-Jan-22
WIP : 62734

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 11/1/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS CHUA JIA MIN
ADDRESS : 1 FERNVLE CLOSE
#19-01
SINGAPORE 797485
TELEPHONE : HP +65 82884029
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210105202
VEHICLE NO : SLX 2317 E
MODEL CODE : AUDI Q3 1.4 TFSI S
MODEL YEAR : 31/8/2021
ENGINE NO : CZD C49833
CHASSIS NO : WAUZZZF30M1155597
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 9-Jan-22
PLACE OF ACCIDENT : SENGKANG EAST ROAD
U-TURN

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLX 2317 E

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING ATD.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	250 ✓
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. VACUUM AND REGAS.	S/N \$ 2,200.00	X 2200 ✓
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDERS AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSTION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 4,800.00	500 · 2000
5	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$ 2,500.00	550 ✓
6	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N \$ 280.00	X
7	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	192 ✓
TOTAL LABOUR CHARGES		: \$ 11,044.00	

5 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 1323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO.SLX 2317 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted.</i>	1	\$ 1,008.00	✓ 806.40
2	FRONT BUMPER CONNECTING PIECE <i>? mis</i>	1	\$ 145.00	✓ 115.60
3	FRONT BUMPER CLOSING ELEMENT - LH <i>Damaged</i>	1	\$ 59.00	✓ 46.64 ✓
4	FRONT BUMPER GRILLE - CENTER <i>ut</i>	1	\$ 217.00	✓ 173.20
5	FRONT BUMPER GRILLE COVER - LOWER <i>? NN</i>	1	\$ 51.00	✗
6	FRONT BUMPER GRILLE - LH <i>ut</i>	1	\$ 110.00	✓ 88
7	FRONT BUMPER CLOSING ELEMENT <i>? Dented</i>	1	\$ 190.00	✓ 151.60 ✓
8	FRONT BUMPER SPOILER <i>torn</i>	1	\$ 383.00	✓ 306.40
9	FRONT BUMPER BRACKET <i>? NN</i>	1	\$ 21.00	✗
10	FRONT BUMPER AIR GUIDE GRILLE - LH <i>? mis</i>	1	\$ 153.00	✓ 122
11	RADIATOR GRILLE <i>cracked</i>	1	\$ 1,433.00	✓ 1146.40
12	RADIATOR STRIKER PLATE <i>? cracked</i>	1	\$ 244.00	✓ 194.80 ✓
13	RADIATOR COVER CAP <i>? NN</i>	1	\$ 45.00	✗
14	"360" CAMERA <i>the new</i>	1	\$ 1,141.00	✗
15	FRONT BUMPER FOAM FILLER PIECE <i>? NN</i>	1	\$ 102.00	✗
16	FRONT BUMPER REINFORCEMENT BEAM <i>the new</i>	1	\$ 916.00	✓ 732.40 Damaged ✓
17	FRONT BUMPER GUIDE SECTION - LH <i>? NN</i>	1	\$ 39.00	✗
18	FRONT BUMPER TOP COVER <i>? nec</i>	1	\$ 123.00	✓ 98 ✓
19	"CAUTION" STICKER <i>? Nec</i>	1	\$ 14.00	✓ 10.88 ✓
20	AIR COND STICKER <i>? Nec</i>	1	\$ 8.00	✓ 5.68 ✓
SUB TOTAL SPARE PARTS		:	\$ 6,402.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO.SLX 2317 E

DAMAGED PARTS & PRICES				
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT PARKING AID SENSOR	2	TBC	
22	FRONT PARKING AID SENSOR SEAL RING	4	\$ 9.00	
23	FRONT BUMPER WIRING SET	1	\$ 676.00	
24	HORN - LH	1	\$ 137.00	109.60 ✓
25	HORN SUPPORT - LH	1	\$ 22.00	17.04 ✓
26	FRONT FENDER - LH	1	\$ 1,286.00	
27	FRONT FENDER BRACE - LH	1	\$ 88.00	
28	FRONT FENDER BRACKET - LH	1	\$ 32.00	
29	FRONT WHEEL HOUSING LINER - LH	1	\$ 240.00	191.60 ✓
30	FRONT WHEEL HOUSING LINER COVER - LH	1	\$ 16.00	
31	HEADLIGHT MOUNTING - LH	1	\$ 118.00	94.40 ✓
32	HEADLIGHT - LH	1	\$ 5,589.00	4471.20
33	LIFT CYLINDER - LH	1	\$ 210.00	167.60 ✓
34	LIFT CYLINDER HOSE	1	\$ 80.00	63.44 ✓
35	WATER RESERVOIR	1	\$ 220.00	176
36	LOCK CARRIER	1	\$ 1,272.00	1017.60 ✓
37	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 7.00	
38	A/C CONDENSER	1	\$ 551.00	
39	RADIATOR COOLANT	6	\$ 266.00	212.64 ✓
40	RADIATOR AIR GUIDE - LH	1	\$ 38.00	29.76 ✓
SUB TOTAL SPARE PARTS		:	\$ 10,857.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLX 2317 E

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
41	RADIATOR AIR GUIDE - UPPER / LOWER ALP 441	2	\$	84.00	X 66.08 ✓ deformed
42	FRONT WHEEL ARCH COVER - LH / RH LH at, RH new	2	\$	536.00	✓ 428.80
43	FRONT NOISE INSULATION new	1	\$	397.00	✓
44	FRONT NO PLATE new	S/N	\$	60.00	✓
45	SUNDRIES ? NN		\$	350.00	? X
TOTAL SPARE PARTS		:	\$	18,686.00	
TOTAL LABOUR CHARGES		:	\$	11,044.00	
GRAND TOTAL		:	\$	29,730.00	

ALL CHARGES ARE NOT INC' USIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1193
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Adrian King.
10/01/22
:
:
:
:
:
: Not Authorised, 03 Days.

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT