

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email : mg3solution@gmail.com

TO	: CHINA TAIPING	DATE	: 10-Jan-22
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SLD3662G	Asher	
MODEL	: HONDA SHUTTLE 1.5G		
CHASSIS NO	:		
<u>ACCIDENT DETAILS</u>		DATE	: 29-Dec-21
		TIME	: 13:30HR
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Debonat.</i>	1	\$ 1,250.00	\$ 1,250.00
2	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 64.50	\$ 129.00
3	REAR BUMPER REFLECTOR RH	1	\$ 98.00	\$ 98.00
4	REAR BUMPER REFLECTOR HOUSING RH <i>new</i>	1	\$ 113.20	\$ 113.20
5	REAR BUMPER SIDE SPONGE RH	1	\$ 102.32	\$ 102.32

1120
896

TOTAL PRICE	\$ 1,692.52
LESS 20%	\$ 338.50
SUB TOTAL PRICE	\$1,354.02

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIPS <i>new</i>	1	\$ 20.00	\$ 20.00
2	REVERSE SENSOR <i>new</i>	1	\$ 220.00	\$ 220.00

20 TOTAL \$240.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 600.00	200	

2	TO SPRAY PAINT AFFECTED AREA	\$	600.00	200	
3	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$	120.00	50	
4	WIRING CHECK	\$	150.00	X	

TOTAL

\$1,470.00

ESTIMATE REPORT

TOTAL PARTS COST : \$1,594.02
TOTAL LABOUR COST : \$1,470.00
TOTAL REPAIR COST : \$3,064.02

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :
PART BY PART OR LUMP SUM :
DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

ASO

Adrian G

1/s 10/01/22.

02 Days.

total: 1366

4/s: 1.1K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: