

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111

FAX: 62247175

ATTN: Motor Claim Department

Estimate No: EST2200011

Date: 11 Jan 2022

Veh Reg No: SNB1965H

Make/Model: HYUNDAI CN7
AVANTE 1.6 DOHC CVT
S/R

Chasis No: KMHLN41ETNU184940

Reg. Date: 07/09/2021

Your Ref No: GBJ4797G

Claim Type: Third Party

Accident Date: 09/01/2022

TP Veh Reg No: GBJ4797G

Xiao Tony

Estimate Repair Cost to Vehicle No :SNB1965H

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1 PC BONNET <i>Distorted</i>	2,253.80	✓
2	2 PCS BONNET HINGES <i>Men.</i>	165.80	+
3	2 PCS BONNET SIDE RUBBER <i>Men</i>	52.40	+
4	1 PC BONNET TRIM <i>Men</i>	221.10	+
5	1 PC BONNET LOCK <i>Dist</i>	129.90	✓
6	1 PC BONNET LOCK GARNISH <i>cracked</i>	240.90	✓
7	1 PC FRT AIR CLEANER AIR DUCT <i>cracked</i>	278.10	✓
8	1 PC FRT GRILLE <i>cracked</i>	896.60	✓
9	1 PC FRT GRILLE BASE <i>cracked</i>	173.30	✓
10	1 PC FRT FENDER <i>Dist</i>	1,227.70	✓
11	1 PC FRT FENDER COWLING <i>RH torn</i>	194.60	✓
12	1 PC HEADLAMP <i>RH cracked</i>	3,034.90	✓
13	1 PC HEADLAMP LOWER BRACKET <i>RH cracked</i>	69.40	✓
14	1 PC HEADLAMP <i>RH new cracked</i>	3,034.90	✓
15	1 PC FRT BUMPER <i>Distorted</i>	525.80	✓
16	1 PC FRT BUMPER REINFORCEMENT <i>Distorted</i>	695.80	✓
17	1 PC FRT BUMPER SPONGE <i>cracked</i>	140.70	✓
18	1 PC FRT BUMPER GRILLE <i>Men</i>	178.90	+
19	1 PC FRT NUMBER PLATE BASE <i>cracked</i>	56.70	✓
20	1 PC FRT BUMPER LOWER GARNISH <i>Men</i>	181.40	+
21	1 PC FRT LOGO <i>Men</i>	64.20	✓
22	2 PCS FRT BUMPER SIDE RETAINERS <i>RH Dist</i>	64.80	32.40
23	1 PC FRT BUMPER INNER GARNISH <i>RH new</i>	91.60	+
24	1 PC FRT BUMPER FOG LAMP COVER <i>RH cracked</i>	124.20	✓
25	1 PC FRT BUMPER CENTRE CHROME <i>new</i>	166.70	✓
26	1 PC FRT BUMPER LOWER SIDE GARNISH <i>RH Dist</i>	52.70	✓
27	1 PC FRT WIPER WATER TANK <i>Men</i>	67.20	+
28	1 PC FRT WIPER WATER TANK MOTOR <i>Men</i>	126.90	+

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Estimate No: EST2200011

Date: 11 Jan 2022

Veh Reg No: SNB1965H
Make/Model: HYUNDAI CN7
AVANTE 1.6 DOHC CVT
S/R

Chasis No: KMHLN41ETNU184940

Reg. Date: 07/09/2021

Your Ref No: GBJ4797G

Claim Type: Third Party
Accident Date: 09/01/2022
TP Veh Reg No: GBJ4797G

Estimate Repair Cost to Vehicle No :SNB1965H

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
29	3 PCS FRT PARKING SENSORS <i>2 pieces dented</i>	597.60	358.40
30	1 PC FRT CHROME MOULDING RH <i>2x</i>	196.70	2
31	1 PC FRT TOWING COVER <i>new</i>	31.90	x
32	1 PC FRT SUPPORT PANEL <i>could</i>	949.30	✓
33	1 PC AIR CONDENSER <i>not warped</i>	745.00	✓
34	2 PCS AIR CONDENSER SIDE TRIM <i>RH torn</i>	198.00	95
35	1 PC RADIATOR <i>3 new</i>	636.90	x
36	1 PC RADIATOR FAN ASSY	677.60	x
		18,544.00	
	Less 20%	3,708.80	14,835.20
Special Net			
37	1 SET BONNET TRIM CLIPS <i>new</i>	60.00	x
38	1 SET BONNET LOCK GARNISH CLIPS <i>new</i>	40.00	20
39	1 SET FRT GRILLE CLIPS <i>new</i>	40.00	20
40	1 SET FRT FENDER COWLING CLIPS RH <i>new</i>	60.00	30
41	1 SET FRT BUMPER GRILLE CLIPS <i>new</i>	30.00	10
42	1 PC FRT NUMBER PLATE <i>dent</i>	50.00	✓
43	1 SET FRT BUMPER INNER GARNISH CLIPS RH <i>new</i>	30.00	x
44	1 SET FRT BUMPER CLIPS <i>new</i>	60.00	30
		370.00	370.00
Labour			
45	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,600.00	1400
46	1 TO SPRAY PAINTING	1,200.00	800
47	1 TO SPRAY UNDERSEAL	100.00	40
48	1 TO REPLACE FRONT PARKING SENSORS	80.00	50
49	1 TO REFILL AIRCON GAS	120.00	80
50	1 TO CHECK WIRING	50.00	30

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Estimate No: EST2200011
Date: 11 Jan 2022

Veh Reg No: SNB1965H
Make/Model: HYUNDAI CN7
AVANTE 1.6 DOHC CVT
S/R

Chasis No: KMHLN41ETNU184940
Reg. Date: 07/09/2021
Your Ref No: GBJ4797G

Claim Type: Third Party
Accident Date: 09/01/2022
TP Veh Reg No: GBJ4797G

Estimate Repair Cost to Vehicle No :SNB1965H

Quantity	Description	List Price	Amount
		SS	SS
51	1 TO PROGRAMME AND RESET	350.00 2250	150
		3,500.00	3,500.00
		Total	S\$ 18,705.20
		Add GST @ 7%	1,309.36
		Total Amount Payable	S\$ 20,014.56

TOTAL: SINGAPORE DOLLAR TWENTY THOUSAND FOURTEEN AND CENTS FIFTY SIX ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

AT

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For Kang Car Repairers Pte Ltd

Alina
AUTHORISED SIGNATURE

Adrian
P/P 11/01/22

08 Days
total: 15035.36 (P/P)