

TPAIG.

Xiao Tony

SLD8168 J. 2021 Feb.

BMW S20i 1998cc

WBAZAG0X0W X08559.

		1445
Rear Bumper	Delhd	1658 ✓
	du	50 ✓
Rear Bumper Clips.		
Rear Bumper Side Holder x 02	x4 M	$95 \times 2 = 190$ X
Rear Bumper Corner Garnish	Delhd	328. ✓
Rear Bumper Tow Cover	x4 M	40 X
Rear Bumper Reflector x 02	M	$68 \times 2 = 136$ X
Rear Bumper Reinforcement	Dented	652 568
Rear Bumper Centre Guide.	x4 M	204. X
Rear Bumper Kick Sensor	x4 M	405 X
Rear Bumper Kick Sensor Cover	cracked	259. ✓
Rear Bumper Undercover	M	214 X
Reverse Sensor x 04	2 pieces delhd	$250 \times 4 = 1000$ 500
Reverse Sensor Holder x 04	M	$20 \times 4 = 80$ ✓
Rear End Panel	Paint	995 X
Rear End Panel Sealant	M	60(SN) X

SLD 8168 J.

Taillamp x 02

XP
m

740 x 2 = 1480. X.

3230

2907

Panel Beating

Spry Painting

Wiring

To remove reverse sensor

To remove upholstery

To perform diagnostic test.

To spray tuff coat

~~800~~ 500

~~600~~ 500

~~50~~ 30

~~100~~ 60

~~150~~ 40

~~200~~ 100

~~150~~ 40

1270

total 4177

L/S: 3.3K.

03 Days

3.3K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: