

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06516

Vehicle Insured : SKC7803H
Accident Date : 07-Jan-2022

Date : 07-Jan-2022

Our Ref : 022007 (CHINA) / CHAN

PAGE : 1

TAN QUEE LENG
27 HAZEL PARK TERRACE
#11-08
Singapore 678949

Not Authorized
U/P &
Recovery After Point
Today

ESTIMATED COST OF REPAIR FOR NISSAN QASHQAI SLP214Z

1 pc Bonnet		By 1,167.40	n	—
1 pc Front grille		577.60	n	?
1 pc Front grille logo		79.90	n	?
6 pcs Front grille clip		27.00	n	?
2 pcs Headlamp		1,346.80	n	—
1 pc Front bumper fascia		751.20	n	—
1 pc Front bumper reinforcement		831.40	n	?
1 pc Front bumper sponge		240.90	n	?
2 pcs Front bumper side retainer	@ S\$ 74.20	148.40	n	X
1 pc Tail gate		3,368.90	n	—
1 pc Tail gate outer garnish		352.10	n	X
1 pc Tail gate glass moulding		90.00	n	—
1 pc Rear bumper fascia		796.70	n	—
1 pc Rear bumper reinforcement		691.50	n	?
1 pc Rear bumper sponge		155.60	n	?
1 pc Rear bumper tow cover		20.00	n	—
2 pcs Rear bumper side retainer	old @ S\$ 39.00	78.00	n	—
1 pc Rear end panel		482.60	n	?
1 pc End panel top garnish		175.00	n	?
1 pc Rear o/s fender arch garnish		540.50	n	—

11,921.50

Less 10% : 1,192.15

1 pc Front no.plate with box
1 pc Rear no.plate with box
1 pc Rear w/s glass sealant

10,729.35
60.00 sn X
60.00 sn X
60.00 sn
405m

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SKC7803H

Page : 2

1 pc Rear bumper reverse sensor(set)	300.00	sn ✓
1 pc Rear bumper clip (set)	40.00	sn —
To rewire damaged parts and refocus headlamp beam.	20.00	✓
To remove & refix rear windscreen glass and conduct water leak test.	150.00	120 ✓
To remove roof lining, front and rear seats, trim board and carpet	120.00	80 ✓
To remove air con condenser, pipes and drier, vacuum and to recharge gas	120.00	90 ?
To apply undersealing	60.00	7
To putty and spray replaced parts	1,300.00	120 ✓
To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts	1,000.00	90 ✓
Total :	S\$14,019.35	=====

Singapore Dollars Fourteen Thousand and Nineteen and Cents Thirty Five Only

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: