

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SKC7803H

Page : 2

1 pc Rear bumper reverse sensor(set)
1 pc Rear bumper clip (set)

nd 300.00 sn ✓
nd 40.00 sn —

To rewire damaged parts and refocus
headlamp beam.

20.00 ✓

To remove & refix rear windscreen
glass and conduct water leak test.

150.00 *120d*

To remove roof lining, front and
rear seats, trim board and carpet

120.00 *80d*

To remove air con condenser, pipes
and drier, vacuum and to recharge
gas

na 120.00 *88*

To apply undersealing

60.00 ✓

To putty and spray replaced parts

1,300.00 *120d*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

1,000.00 *90d*

Total : S\$14,019.35
=====

Singapore Dollars Fourteen Thousand and Nineteen
and Cents Thirty Five Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SKC7803H (CHINA)

Date : 13-01-2022

Accident Date : 07-01-2022

Our Ref : 022007 / CHAN

TAN QUEE LENG

C/O ALAN'S UNITED AUTO PTE LTD

SUPPLEMENTARY ITEM PRICE FOR NISSAN QASHQAI SLP214Z

2 PCS REAR BUMPER REINFORCEMENT BRACKET @ \$141.00

Bt ✓

\$282.00N ✓

LESS 10% \$28.20

\$253.80

Singapore Dollars Two Hundred Fifty Three And Cents Eighty Only