



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD	INV No.	AC2202679
3 ANSON ROAD #16-00	INV Date	11/05/2022
SPRINGLEAF TOWER	Reference	CC6/CTI22000398/Kga3q2
SINGAPORE 079909	Code	CTI

PROFESSIONAL SERVICE FEE

Vehicle No.	SGG 6813L
Insured Veh.	SKC 7803H
Claim No.	SNM22D200177
Policy No.	DMPCSNW00020752101
Accident Date	07/01/2022
Inspection Date	07/01/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Ref: CC6/CTI22000398/Kga3q2 Date: 11/05/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKC 7803H	Veh. Inspected	SGG 6813L
Policy No.	DMPCSNW00020752101	Coverage (\$)	0.00
Claim No.	SNM22D200177	Excess (\$)	0.00
Assign From		Assign Date	07/01/2022
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA ESTIMA (A)	c.c	2362
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	ACR507137371	Colour	METALLIC GREY
Odometer	78445 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/50 R18	MICHELIN	7 mm
L/H Front Tyre	235/50 R18	MICHELIN	7 mm
R/H Rear Tyre	235/50 R18	MICHELIN	7 mm
L/H Rear Tyre	235/50 R18	MICHELIN	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	07/01/2022	Inspection Date	07/01/2022
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGG 6813L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAIL GATE	BENT	1,490.10	1,490.10
1	TAIL GATE GLASS MOULDING	NECESSARY	91.20	91.20
1	TAIL GATE 'ESTIME' EMBLEM	NECESSARY	44.20	44.20
1	TAIL GATE LOGO	NECESSARY	66.80	66.80
1	TAIL GATE INNER TRIM COVER	MTG CRACKED	476.60	476.60
1	REAR END PANEL	BENT	625.50	625.50
1	END PANEL TOP GARNISH	MTG CRACKED	260.50	260.50
6	END PANEL TOP GARNISH CLIP @\$9.60	NECESSARY	57.60	57.60
1	END PANEL LOWER GARNISH	DISTORTED	175.80	175.80
2	REAR FENDER INNER TRIM @\$763.80	DEFORMED	1,527.60	1,527.60
1	REAR BUMPER FASCIA	BENT	541.70	541.70
2	REAR BUMPER SIDE RETAINER (L) @\$52.20	SERVICEABLE	104.40	-
2	REAR BUMPER SIDE RETAINER (S) @\$45.30	SERVICEABLE	90.60	-
2	REAR BUMPER SPONGE @\$67.40	CRACKED / DEFORMED	134.80	134.80
2	REAR BUMPER REFLECTOR @\$53.90	SERVICEABLE	107.80	-
	LESS 25% DISCOUNT		-1,448.80	-1,373.10
			4,346.40	4,119.30
<u>SPECIAL NETT ITEMS</u>				
1	REAR NO PLATE WITH BOX (SN)	BENT	60.00	45.00
1	REAR W/S GLASS SEALANT (SN)	NECESSARY	60.00	40.00
1	REAR BUMPER REVERSE SENSOR (SN)	DENTED	300.00	300.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	40.00	40.00
			460.00	425.00
<u>LABOUR</u>				
	TO REMOVE & REFIX REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.		150.00	120.00
	TO REMOVE ROOF LINING ,FRONT AND REAR SEATS,TRIM BOARD AND CARPET.		120.00	100.00
	TO APPLY UNDERSEALING .		60.00	60.00
	TO PUTTY AND SPRAY REPLACED PARTS.		700.00	650.00

Report Ref No. CC6/CTI22000398/Kga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE ,CUT -OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN,REFIX AND TO RENEW ABOVE PARTS.		800.00	680.00
			1,830.00	1,610.00
GRAND TOTAL			6,636.40	6,154.30
RECOMMENDED COST OF REPAIRS				6,154.30

Report Ref No. CC6/CTI22000398/Kga3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGG 6813L

INSPECTION







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGG 6813L

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGG 6813L

RE-INSPECTION

