

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 16235

Vehicle Insured : SKC7803H
 Accident Date : 07-Jan-2022

Date : 25-Jan-2022

Our Ref : 022008 (CHINA) / CHAN

PAGE : 1

EL-MANDATE ADVISORY PTE LTD
 229 MOUNTBATTEN ROAD #01-16
 MOUNTBATTEN SQUARE
 Singapore 398007

FINAL REPAIR COST FOR TOYOTA ESTIMA SGG6813L
 =====

1 pc Tail gate		1,490.10	
1 pc Tail gate glass moulding		91.20	
1 pc Tail gate "ESTIMA" emblem		44.20	
1 pc Tail gate logo		66.80	
1 pc Tail gate inner trim cover		476.60	
1 pc Rear end panel		625.50	
1 pc End panel top garnish		260.50	
6 pcs End panel top garnish clip	@ S\$ 9.60	57.60	
1 pc End panel lower garnish		175.80	
2 pcs Rear fender inner trim	@ S\$763.80	1,527.60	
1 pc Rear bumper fascia		541.70	
2 pcs Rear bumper sponge	@ S\$ 67.40	134.80	

		5,492.40	
	Less 25% :	1,373.10	

			4,119.30
1 pc Rear no.plate with box			45.00 sn
1 pc Rear w/s glass sealant			40.00 sn
1 pc Rear bumper reverse sensor			300.00 sn
1 pc Rear bumper clip (set)			40.00 sn
To remove & refix rear windscreen glass and conduct water leak test.			120.00
To remove roof lining, front and rear seats, trim board and carpet			100.00

Con't Page 2 ...