

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SKC7803H
 Accident Date : 07-Jan-2022

No. : 06515

Date : 07-Jan-2022

Our Ref : 022008 (CHINA) / CHAN

PAGE : 1

EL-MANDATE ADVISORY PTE LTD
 229 MOUNTBATTEN ROAD #01-16
 MOUNTBATTEN SQUARE
 Singapore 398007

NOT Authorized
& 6154.30
Mercury After Paint
6 days

ESTIMATED COST OF REPAIR FOR TOYOTA ESTIMA SGG6813L
 =====

1 pc Tail gate			<i>R</i>	1,490.10	—
1 pc Tail gate glass moulding			<i>Mc</i>	91.20	—
1 pc Tail gate "ESTIMA" emblem			<i>Mc</i>	44.20	—
1 pc Tail gate logo			<i>Mc</i>	66.80	—
1 pc Tail gate inner trim cover			<i>Mc/CM</i>	476.60	—
1 pc Rear end panel			<i>R</i>	625.50	—
1 pc End panel top garnish			<i>Mc/CM</i>	260.50	—
6 pcs End panel top garnish clip	@ S\$ 9.60		<i>Mc</i>	57.60	—
1 pc End panel lower garnish			<i>Mc</i>	175.80	—
2 pcs Rear fender inner trim	<i>Defom</i> @ S\$763.80		<i>R</i>	1,527.60	—
1 pc Rear bumper fascia			<i>R</i>	541.70	—
2 pcs Rear bumper side retainer (L)	<i>Mc</i> @ S\$ 52.20		<i>Mc</i>	104.40	X
2 pcs Rear bumper side retainer (S)	<i>Mc</i> @ S\$ 45.30		<i>Mc</i>	90.60	X
2 pcs Rear bumper sponge	<i>Mc/Defom</i> @ S\$ 67.40			134.80	—
2 pcs Rear bumper reflector	@ S\$ 53.90		<i>R</i>	107.80	X
				5,795.20	
	Less 25% :			1,448.80	

- 1 pc Rear no.plate with box
- 1 pc Rear w/s glass sealant
- 1 pc Rear bumper reverse sensor
- 1 pc Rear bumper clip (set)

R 4,346.40 *4512*
Mc 60.00 *sn*
Mc 60.00 *sn*
Mc 300.00 *sn*
Mc 40.00 *sn*

To remove & refix rear windscreen glass and conduct water leak test.

150.00 *12d*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SKC7803H

Page : 2

To remove roof lining, front and rear seats, trim board and carpet

100l
120.00

To apply undersealing

60.00 ✓

To putty and spray replaced parts

700.00 *65d*

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts

800.00 *68d*

Total : S\$ 6,636.40
=====

Singapore Dollars Six Thousand Six Hundred and Thirty Six and Cents Forty Only