

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/EG122000404/EVF3E2

**Date:** 18/05/2022

### REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:  
**Claimant Vehicle No :** SCX1489E **Insured Vehicle No :** SLD3901S  
Date of Loss: 07/01/2022 Nature of Claim: TP Claim No: CDMPG22000046

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SCX1489E**  
Make & Model: INFINITI Q50, 2.0 T (R18) EU6 NAV (A) Engine No: 274AE124604A  
Reg. Date: 23/12/2020 (Man. Year: 2019) Chassis No: JN1BCAV37Z0590082  
Colour: Silver Odometer: 20818 km  
Engine Capacity: 1991 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/50 R18 Rear Tyre Size: 225/50 R18  
Front Left Side: Dunlop 5 mm Rear Left Side: Dunlop 5 mm  
Front Right Side: Dunlop 5 mm Rear Right Side: Dunlop 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,755.90	0.00	2,755.90	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,398.00	2,098.00	300.00	12.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>5,153.90</b>	<b>2,098.00</b>	<b>3,055.90</b>	<b>59.29</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>360.77</b>	<b>146.86</b>	<b>213.91</b>	<b>59.29</b>
<b>Nett Amount (S\$)</b>	<b>5,514.67</b>	<b>2,244.86</b>	<b>3,269.81</b>	<b>59.29</b>

### INSPECTION

Date of Assignment: 12/01/2022  
Date Inspected: 18/01/2022 Inspected At: Wearnes Automotive Pte Ltd (Leng Kee)  
45 Leng Kee Road  
Singapore 159103  
Estimated Period of Repair: 3.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$122.80 NETT)

# REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 May 2022)
Parts:	143	INFINITI Q50 2.0 T (R18) EU6 NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCX1489E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACE-RR BUMPER	Repair	1,347.70 FS	*- FS
2	1		*BRACKET-BUMPER RR RH	* Check	61.40 FS	*- FS
3	1		*BUMPER REAR RH BRACK	* Check	61.40 FS	*- FS
4	1		*REINF-BUMPER RR	Not Necessary	955.80 FS	*- FS
5	4		*BRACKET SONAR RR- Q5	Not Necessary	329.60 FS	*- FS
Total Parts (S\$)						2,755.90
						0.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE REAR BUMPER, ETC	New	1,000.00	800.00
2	TO SPRAY REAR BUMPER	New	900.00	800.00
3	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	498.00	498.00
<b>Gross Labour Cost (\$)</b>			<b>2,398.00</b>	<b>2,098.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >