

ASS. REC. BY:

Steve

REF:

CS/EG1220004-04/ERF3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SLD 3901S

Policy No. _____

Claims No. CDMPG22000046

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No:

SCX 1489 E

Yr Regn:

23/12/20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

INFINITI Q50

c.c. 1991

Colour

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

20818

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JN1BCAV3720590082

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

275/50R18

R:

11

BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/

TOYO/YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

7/1/22

D.O.I.

18/1/22

Survey held at

Wearnes

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear RH

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV-14.28

11/4/22

Submit preli report-revised fig \$2098 check items \$122.80

Date/Time, File Pass to?



: Preli. Report



: Final Report

1)

Date/Time, File Return to?

2) 11/4/22-typist

Report Format: _____

Lump Sum / I.B.I. (\$) _____

Days Of Repair: 3

Resurvey No. of Trip: _____

Add Fee:



: Site Insp (\$ _____)



: Interview (\$ _____)



: Tech. Invs (\$ _____)



: Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS \$1

Photos

Others

TOTAL

Store (LKK)
18/1/22, 10.00am
MR PL
PIP
by BL
3 d/s
** take photo partly rear bumper*

SERVICE ESTIMATE

86255 - C00001
 Mr Lim Peng Choon
 132A Hillview Avenue
 #05-05 Mon Trosa
 Singapore 669604

SL: SERVICE SALES - PC

Closed by : Juan Paulo Bongon Ba
 Svc Consultant :
 Remarks : Mr Lim Peng Choon

GST Reg.No: M28920628X
 Inv.No. . . : B&P 0 Page 1
 Inv.date. . : 11/01/2022
 WIP No. . . : 63507
 Veh.In/Out:
 *Tel.No. . . : Mobile: 94759943
 Reg.No. . . : SCX1489E
 Reg.date . . : 23/12/2020
 Mileage ... : 0
 Chassis No: JN1BCAV37Z0590082

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER, ETC	0	1000.00	0	800	1,000.00	S
800	TO SPRAY REAR BUMPER	0	900.00	0	800	900.00	S
280	TO CHECK WIRING INCLUDE	0	498.00	0		498.00	S
RESETTING OF ALL ELECTRICAL MODULES							
	FACE-RR BUMPER <i>X R</i>	1.0 EA	1347.70			1,347.70	S
	BRACKET-BUMPER RR RH <i>-</i>	1.0 EA	61.40			61.40	S
	BUMPER REAR RH BRACK	1.0 EA	61.40			61.40	S
	REINF-BUMPER RR <i>X nn</i>	1.0 EA	955.80			955.80	S
	BRACKET SONAR RR- Q5 <i>X nn</i>	4.0 EA	82.40			329.60	S

Gross Total. 5,153.90
 Net..... 5,153.90
 GST @ 7.0% 360.77
 Total..... 5,514.65
 Paid..... 0.00
 Please Pay.. 5,514.65

Labour Total 2,398.00
 Parts Total 2,755.90
 Package Total 0.00
 GST: S=Standard, O=OutOfScope; Z=ZeroRated

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Wearnes Automotive Pte. Ltd.
 45 Leng Kee Road, Singapore 159103 T 6430 4700 www.wearnes.com

Date:
 Co reg no: 199501400R / GST reg no: M28920628X