

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/HLA22000405/EQF3E2

**Date:** 08/02/2022

### REFERENCE

Handling Insurer: HL Assurance Pte Ltd Policy No: MP317436  
Claimant Vehicle No : SLP2755R Insured Vehicle No : SBZ312P  
Date of Loss: 09/01/2022 Nature of Claim: TP Claim No: MPC03093

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLP2755R**  
Make & Model: VOLKSWAGEN SHARAN, 2.0 TSI (A) Engine No: DED035938  
Reg. Date: 30/12/2020 (Man. Year: 2020) Chassis No: WVVZZZ7NZLV016070  
Colour: Grey Odometer: 13740 km  
Engine Capacity: 1984 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18  
Front Left Side: Bridgestone 4 mm Rear Left Side: Bridgestone 4 mm  
Front Right Side: Bridgestone 4 mm Rear Right Side: Bridgestone 4 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,448.59	5,616.94	1,831.65	24.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,990.00	5,450.00	4,540.00	45.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>17,438.59</b>	<b>11,066.94</b>	<b>6,371.65</b>	<b>36.54</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,220.70</b>	<b>774.69</b>	<b>446.01</b>	<b>36.54</b>
<b>Nett Amount (S\$)</b>	<b>18,659.29</b>	<b>11,841.63</b>	<b>6,817.66</b>	<b>36.54</b>

### INSPECTION

Date of Assignment: 12/01/2022  
Date Inspected: 13/01/2022 Inspected At: Volkswagen Centre Singapore (HQ)  
247 Alexandra Road  
Singapore 159934  
Estimated Period of Repair: 5.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 08 Feb 2022)
<b>Parts:</b> M1-MPV	VOLKSWAGEN SHARAN 2.0 TSI (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLP2755R)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR BUMPER PRIMED	Dented	1,664.60 FS	*1,664.60 FS
2	1		*SPOILER SATIN BLACK	Not Necessary	327.20 FS	*- FS
3	1		*ATTACHMENT STRIP	Not Necessary	209.81 FS	*- FS
4	1		*BUMPER BRACKET	Not Necessary	856.49 FS	*- FS
5	1		*GUIDE PIECE	Not Necessary	85.78 FS	*- FS
6	1		*GUIDE PIECE	Not Necessary	85.78 FS	*- FS
7	1		*REAR TRUNK LID	Dented	3,296.80 FS	*3,296.80 FS
8	1		*INSCRIPTION CHROME SHARAN	Necessary	96.05 FS	*96.05 FS
9	1		*VW SIGN BLACK HIGH GLOSS /	Necessary	139.85 FS	*139.85 FS
10	2		*SENSOR BRACKET	Not Necessary	56.04 FS	*- FS
11	2		*SENSOR BRACKET	Not Necessary	56.04 FS	*- FS
12	1		*BONDING AGENT FOR PLASTIC	Not Necessary	68.71 FS	*- FS
13	1		*2K-PLASTIC ADHESIVE	Not Necessary	85.80 FS	*- FS
14	2		*1K WINDOW ADHESIVE	Necessary	102.70 FS	*102.70 FS
15	1		*PRIMER	Necessary	30.22 FS	*30.22 FS
16	1		*ACTIVATOR FOR PRECOATED W	Necessary	26.23 FS	*26.23 FS
17	1		*ADHESIVE REMOVER	Necessary	120.06 FS	*120.06 FS
18	2		*APPLICATOR	Necessary	22.32 FS	*22.32 FS
19	1		*REAR NUMBER PLATE	Bent	80.00 FS	*80.00 FS
20	1		*PACKING ADHESIVE	Necessary	32.83 FS	*32.83 FS
21	2		*RIVETTED CAP NUT	Necessary	5.28 FS	*5.28 FS

F=Franchise part. S=SpcNett.

<b>Total Parts (S\$)</b>	<b>7,448.59</b>	<b>5,616.94</b>
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR	New	280.00	280.00
2	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
3	LABOUR	New	3,360.00	1,680.00
4	SPRAY PAINTING	New	3,200.00	1,600.00
5	RE-REINSTALLED REAR WSCREEN	New	840.00	840.00
6	RE-REINSTALLED REAR LAUGAGGE TRIM	New	840.00	0.00
7	TRANSFER BOOT LID PARTS	New	840.00	420.00
8	CHECK WATER LEAKAGE	New	150.00	150.00
			<b>Gross Labour Cost (\$)</b>	<b>9,990.00</b>
				<b>5,450.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >