



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS3/SMO21010587/Kqf3e2-1	
			Date: 17/02/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLU 8041B	Veh. Inspected	SLU 9717D
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2102879/LOR	Excess (\$)	0.00
	Assign From	LORRIANCE WONG	Assign Date	12/01/2022
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ E 250 (A)	c.c	1796
	Engine No.	HIDDEN	Year of Reg.	2013
	Chassis No.	WDD2120472A660607	Colour	METALLIC DARK GREEN
	Odometer	141300 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	245/35 R19	GOODYEAR	8 mm
	L/H Front Tyre	245/35 R19	GOODYEAR	8 mm
	R/H Rear Tyre	245/35 R19	YOKOHAMA	7 mm
	L/H Rear Tyre	245/35 R19	YOKOHAMA	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	25/09/2021	Inspection Date	08/11/2021
	Survey held at	MJE MOTOR BLK 7 SIN MING IND EST SEC C #01-96 SINGAPORE 575642		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	