

**Section A - Accident Details**

Registration Number	SHB5336T
Case Reference Number	TAX/01/22/2013
Registration Date	26/12/2019
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	FOO HEE YONG (FU QIXIONG)
Type of Accident	Side Swipe
Accident Date and Time	7/1/2022 8:00 PM
Accident Reported Date and Time	8/1/2022 8:32 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24113601
Special Instruction to ARC, if any	TP / FRONT PORTION / NTUC - LKK
Prepared Date and Time	8/1/2022 10:47 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

**Section B - Summary of Repair Estimates**

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,264.00	\$500.00
Total Spray Cost	\$1,890.00	\$600.00
Total Spare Part Cost	\$23,157.32	\$8,678.92
Total Other Cost	\$340.00	\$30.00
<b>TOTAL COST</b>	<b>\$26,651.32</b>	<b>\$9,808.92 (P/P)</b>
<b>Lump Sum Total</b>	<b>\$0.00</b>	<b>\$0.00</b>
Number of Repair Days	7.0	5.0
Prepared / Adjusted By	<b>Boon Chew Tay</b>	<b>RASUL (LKK) / NTUC</b>
ARC / Surveyor Sign Off Date	<b>13/01/2022 9:27 AM</b>	<b>13/01/2022 8:46 AM</b>
Signature		
Remarks	Total number of repair days = 5 days. SUP = + 1 day.	PART BY PART REPAIR / BEFORE PAINT PHOTO .

**Section C - Quotation and Accident Invoice Details**

<b>Quotation Number</b>	QN-2201-0430	<b>Invoice Number</b>	
<b>Quotation Date</b>	31.01.2022	<b>Invoice Date</b>	
<b>Invoice Amount</b>		<b>Prepared Date</b>	

**Section D - Details of Repair Estimates**

**Part 1 - Labour Works**

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT CHASSIS LH	\$250.00	\$100.00
TO REPAIR FRONT PORTION	\$1,014.00	\$400.00
<b>Total Labour</b>	<b>\$1,264.00</b>	<b>\$500.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY FRONT SUPPORT PANEL	\$378.00	\$0.00
TO RESPRAY FRONT HOOD	\$378.00	\$200.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$0.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$1,890.00</b>	<b>\$600.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$30.00
TO REPLACE SUNDRY PARTS	\$200.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
<b>Total Other Costs</b>	<b>\$340.00</b>	<b>\$30.00</b>

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
		52119-47980	COVER, FR BUMPER	1.00	\$521.00	25.00	\$390.75	Replace	Replace	√
		52115-47050	SUPPORT, FR BUMPER RH	0.00	\$80.10	0.00	\$0.00	Replace	Not Given	X
		52116-47050	SUPPORT, FR BUMPER LH	0.00	\$82.30	0.00	\$0.00	Replace	Check	X
		52127-47911	COVER, FR BUMPER RH	0.00	\$30.20	0.00	\$0.00	Replace	Not Given	X
		52128-47910	COVER, FR BUMPER LH	0.00	\$30.20	0.00	\$0.00	Replace	Not Given	X
		52114-47270	BRACKET, FR BUMPER	1.00	\$110.50	25.00	\$82.88	Replace	Replace	√
		53395-47060	SEAL, HOOD TO FR END	0.00	\$85.50	0.00	\$0.00	Replace	Check	X
		53112-47310	GRILLE, RADIATOR	1.00	\$178.60	25.00	\$133.95	Replace	Replace	√
		53101-47100	GRILLE SUB-ASSY	0.00	\$422.50	0.00	\$0.00	Replace	Check	X
		75310-33050	EMBLEM ASSY FRONT	0.00	\$105.80	0.00	\$0.00	Replace	Not Given	X
		53111-47140	GRILLE, SUB -ASSY , 2	0.00	\$160.50	0.00	\$0.00	Replace	Not Given	X
		51451-12120	COVER ASSY, ENGINE	0.00	\$241.90	0.00	\$0.00	Replace	Not Given	X
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace	√
		52535-50060	RETAINER, FR BUMPER, LH & RH	0.00	\$8.80	0.00	\$0.00	Replace	Not Given	X
		52421-47030	PAD, FRONT BUMPER ( NO.1)	1.00	\$40.70	25.00	\$30.53	Replace	Replace	√

**STRIDES Accident Vehicle Repair Estimates**

<b>STRIDES Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 24/01/2022

User ID : PohSuan

	52421-47040	PAD, FRONT BUMPER ( NO.2)	2.00	\$36.00	25.00	\$54.00	Replace	Replace	√
	52712-47040	MOULDING, FRONT BUMPER SIDE, RH	0.00	\$95.60	0.00	\$0.00	Replace	Not Given	X
	52713-47040	MOULDING, FRONT BUMPER SIDE, LH	1.00	\$95.60	25.00	\$71.70	Replace	Replace	√
	52618-47130	ABSORBER, FR BUMPER LOWER	0.00	\$132.70	0.00	\$0.00	Replace	Not Given	X
	52611-47210	ABSORBER, FR BUMPER	1.00	\$80.20	25.00	\$60.15	Replace	Replace	√
	52102-47020	EXTENSION SUB-ASSY, RH	0.00	\$120.10	0.00	\$0.00	Replace	Not Given	X
	52103-47010	EXTENSION SUB-ASSY, LH	0.00	\$120.10	0.00	\$0.00	Replace	Check	X
	52132-47010	REINFORCEMENT FRONT LOWER	0.00	\$246.10	0.00	\$0.00	Replace	Not Given	X
	52021-47110	REINFORCEMENT FRONT UPPER	0.00	\$716.60	0.00	\$0.00	Replace	Check	X
	81185-47890	UNIT , HEADLAMP , LH	1.00	\$2,637.60	10.00	\$2,373.84	Replace	Replace	√
	81145-47890	UNIT , HEADLAMP , RH	0.00	\$2,637.60	0.00	\$0.00	Replace	Not Given	X
	81056-47860	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	0.00	\$3,772.50	0.00	\$0.00	Replace	Not Given	X
	81016-47860	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	0.00	\$3,772.50	0.00	\$0.00	Replace	Not Given	X
	81210-12240	LAMP ASSY, FOG, RH	0.00	\$237.10	0.00	\$0.00	Replace	Not Given	X
	81220-12240	LAMP ASSY, FOG, LH	0.00	\$237.10	0.00	\$0.00	Replace	Check	X
	81935-47070	CORD, FOG LAMP	0.00	\$55.90	0.00	\$0.00	Replace	Not Given	X
	51410-47021	COVER ASSY, ENGINE UNDER CENTER SET	0.00	\$472.40	0.00	\$0.00	Replace	Not Given	X
	51447-47030	COVER, ENGINE UNDER CENTER	0.00	\$98.00	0.00	\$0.00	Replace	Not Given	X
	51443-12110	COVER, ENGINE UNDER SIDE RH	0.00	\$80.10	0.00	\$0.00	Replace	Not Given	X
	51444-12080	COVER, ENGINE UNDER SIDE LH	0.00	\$80.10	0.00	\$0.00	Replace	Not Given	X
	51442-47030	COVER, ENGINE UNDER, REAR	0.00	\$38.20	0.00	\$0.00	Replace	Not Given	X
		NUMBER PLATE FRAME	1.00	\$25.00	0.00	\$25.00	Replace	Replace	√
		NUMBER PLATE	1.00	\$35.00	0.00	\$35.00	Replace	Replace	√
	53301-47110	HOOD SUB-ASSY	1.00	\$983.10	25.00	\$737.33	Replace	Replace	√
	53410-47130	HINGE ASSY, HOOD, RH	1.00	\$58.90	25.00	\$44.18	Replace	Replace	√
	53420-47130	HINGE ASSY, HOOD, LH	1.00	\$58.90	25.00	\$44.18	Replace	Replace	√
	53510-47140	LOCK ASSY, HOOD	0.00	\$135.00	0.00	\$0.00	Replace	Not Given	X
	53289-47090	COVER, RADIATOR	0.00	\$211.50	0.00	\$0.00	Replace	Not Given	X
	53802-47100	FENDER SUB-ASSY, FR , LH	0.00	\$977.80	0.00	\$0.00	Replace	Not Given	X
	53876-47060	LINER, FR FENDER, LH	0.00	\$210.30	0.00	\$0.00	Replace	Not Given	X
	53852-47041	PAD, FR WHEEL LH	0.00	\$59.60	0.00	\$0.00	Replace	Not Given	X
	53205-47900	SUPPORT S/A UPPER,	0.00	\$377.10	0.00	\$0.00	Replace	Not Given	X
	53202-47901	SUPPORT S/A RH	0.00	\$245.10	0.00	\$0.00	Replace	Not Given	X
	53203-47901	SUPPORT S/A LH	0.00	\$245.10	0.00	\$0.00	Replace	Not Given	X
	53028-12050	SUPPORT SUB-ASSY LOWER	0.00	\$409.90	0.00	\$0.00	Replace	Not Given	X
	53213-47050	SUPPORT, RADIATOR UPPER RH	0.00	\$78.90	0.00	\$0.00	Replace	Not Given	X
	53214-47050	SUPPORT, RADIATOR UPPER LH	0.00	\$78.90	0.00	\$0.00	Replace	Check	X
	53217-47031	BRACE, HOOD LOCK SUPPORT	0.00	\$78.30	0.00	\$0.00	Replace	Not Given	X
<b>Total</b>				<b>\$22,130.71</b>		<b>\$4,095.57</b>			

**STRIDES Accident Vehicle Repair Estimates**

<b>STRIDES Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 24/01/2022

User ID : PohSuan

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		53101-47100	GRILLE SUB-ASSY	1.00	\$422.50	25.00	\$316.88	Replace	Replace
		53111-47140	GRILLE, SUB -ASSY , 2	1.00	\$160.50	25.00	\$120.38	Replace	Replace
		52021-47110	REINFORCEMENT FRONT UPPER	1.00	\$716.60	25.00	\$537.45	Replace	Replace
		81056-47860	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	1.00	\$3,772.50	10.00	\$3,395.25	Replace	Replace
		81220-12240	LAMP ASSY, FOG, LH	1.00	\$237.10	10.00	\$213.39	Replace	Replace
<b>Total</b>					<b>5,309.20</b>		<b>4,583.35</b>		

√  
√  
√  
√  
√

8,678.92  
+ 500.00  
+ 630.00  

---

9,808.92