



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0024/2021/JT
DATE : 10-Jan-22
WIP : 62905

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 11/1/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR CHOO KA SING
ADDRESS : 12 KENSINGTON PARK DRIVE
#06-01
SINGAPORE 557325
TELEPHONE : HP +65 96902212
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO :
VEHICLE NO : **SGN 6668 C**
MODEL CODE : AUDI A3 SEDAN 1.4 TFSI
MODEL YEAR : 26/7/2014
ENGINE NO : CXS 203064
CHASSIS NO : WAUZZZ8V0E1041650
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 10-Jan-22
PLACE OF ACCIDENT : JUNCTION OF PUNGGOL PLACE
AND PUNGGOL FIELD

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGN 6668 C

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	X
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 700.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHT. RE-ORGANIZR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,050.00	500
4	TO RESPRAY FRONT BUMPER.	\$ 900.00	550
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 3,202.00	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6341 1183

EMAIL : NORA.KHAIR@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGN 6668 C

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>Repair</i>	1	\$ 2,233.00	+	
2	FRONT BUMPER FIXING PARTS	1	\$ 187.00	+	
3	FRONT BUMPER TRIM COVER - LH / RH <i>3 new</i>	2	\$ 326.00	+	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>2 new</i>	1	\$ 163.00	+	
5	FRONT BUMPER PULL STRAP - LOWER	4	\$ 206.00	+	
6	FRONT BUMPER GUIDE SECTION- LH / RH <i>1 new</i>	2	\$ 78.00	+	
7	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>1 new</i>	2	\$ 218.00	+	
8	RADIATOR GRILLE <i>could</i>	1	\$ 691.00	✓	
9	RADIATOR GRILLE COVER <i>3 new</i>	1	\$ 98.00	+	
10	"CAUTION" STICKER	1	\$ 14.00	+	
11	AIR COND STICKER	1	\$ 8.00	+	
12	FRONT BUMPER FOAM FILLER PIECE <i>2</i>	1	\$ 137.00	+	
13	FRONT BUMPER LOWER COVER	1	\$ 56.00	+	
14	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 795.00	+	
15	HORN RETAINER - LH / RH	2	\$ 400.00	+	
16	FRONT WHEEL HOUSING LINER - LH / RH <i>1 new</i>	2	\$ 338.00	+	
17	HEADLIGHT - LH / RH	2	\$ 5,282.00	+	
18	LIFT CYLINDER - LH / RH	2	\$ 386.00	+	
19	LIFT CYLINDER HOSE	1	\$ 182.00	+	
20	OUTSIDE TEMPERATURE SENSOR BRACKET <i>1 new</i>	1	\$ 19.00	+	
SUB TOTAL SPARE PARTS			\$ 11,817.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHA@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGN 6668 C

ESTIMATE			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	RADIATOR AIR GUIDE - LH / RH	2	\$ 50.00	+
22	RADIATOR SEAL - RH OUTER	1	\$ 8.00	+
23	RADIATOR AIR GUIDE - UPPER CENTER	1	\$ 12.00	+
24	FRONT NO PLATE	S/N	\$ 100.00	✓
25	SUNDRIES		\$ 300.00	?
TOTAL SPARE PARTS		:	\$ 12,287.00	
TOTAL LABOUR CHARGES		:	\$ 3,202.00	
GRAND TOTAL		:	\$ 15,489.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian L*
 SURVEYED DATE : *11/01/22*
 AUTHORISED DATE :
 EXCESS COST :
 LIABILITY :
 REMARKS : *1st Authorized, 03 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
 FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
 PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
 BODY REPAIR MANAGER

ALLAN WU
 CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: