

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0021/2021/ZK
DATE : 10-Jan-22
WIP : 62716

VEHICLE IN WORKSHOP. KINDLY ARRANGE SURVEY 11/01/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR LIM WEI JIE (LIN WEIJIE)
ADDRESS : BLK 227A SUMANG LANE
#15-252
SINGAPORE 821227
TELEPHONE : HP +65 9695 7166
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070139095
VEHICLE NO : **SMV 4752 S**
MODEL CODE : AUDI Q3 SPORTBACK 1.4 TFSI S
MODEL YEAR : 30/9/2020
ENGINE NO : CZD C00124
CHASSIS NO : WAUZZZF34L1123797
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 9-Oct-22
PLACE OF ACCIDENT : FILITER LANE FROM LOR AH SOO TP HPUGANG AVE 3

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMV 4752 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE , CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT,HORNS,OUTSIDE TEMPERATURE SENSOR , HEADLIGHT WASHER ASSY AND FRONT PARKING AID	S/N \$ 480.00	/
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	250
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM, VACUUM AND REGAS	S/N \$ 1,700.00	?
4	TO RENEW LHS FRONT FRONT FENDER INNER AIRCON CONDENSER PIPE.	S/N \$ 280.00	?
5	TO DISMANTLE AND RENEW FRONT BUMPER,BONNET,LHS FRONT FENDERS AND LHS HEADLIGHT.TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 5,600.00	1000
SUB TOTAL LABOUR CHARGES		: \$ 8,460.00	

2 x 500

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMV 4752 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO RESPRAY FRONT BUMPER , FRONT BUMPER LOWER SPOILER , BONNET, HINGES, LHS FRONT FENDER AND BOTH WHEEL ARCH TRIMS	\$ 4,500.00	2050
7	TO TOW BACK THE VEHIVLE FROM ACCIDENT SCENE	S/N \$ 280.00	X
8	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	S/N \$ 384.00	✓
TOTAL LABOUR CHARGES		: \$ 13,624.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 4752 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPE COVER / <i>00</i>	1	\$ 2,670.00	
2	FRONT BUMPER CONNECTING PIECE <i>X</i>	1	\$ 145.00	
3	FRONT BUMPER FIXING PARTS <i>X</i>	1	\$ 414.00	
4	FRONT BUMPE CLOSING ELEMENT - LH / RH <i>?</i>	2	\$ 118.00	
5	FRONT BUMPER TRIM / <i>cut (grey lower)</i>	1	\$ 356.00	
6	FRONT BUMPER GRILLE - CENTER <i>?</i>	1	\$ 217.00	
7	FRONT BUMPER SUPPORT - LH / RH <i>?</i>	2	\$ 50.00	
8	FRONT BUMPER LOWER SENSOR COVER <i>?</i>	1	\$ 51.00	
9	FRONT BUMPER CLOSING ELEMENT <i>?</i>	1	\$ 190.00	
10	FRONT BUMPER SPOILER / <i>cut (grey lower under)</i>	1	\$ 763.00	
11	FRONT BUMPER BRACKET <i>?</i>	1	\$ 21.00	
12	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>?</i>	2	\$ 306.00	
13	FRONT BUMPER AIR GUIDE GRILLE TRIM - LH / RH <i>?</i>	2	\$ 328.00	
14	FRONT PARKING AID SENSOR BRACKET - LH / RH <i>?</i>	2	\$ 50.00	
15	FRONT RADIATOR GRILLE / <i>BR</i>	1	\$ 1,928.00	
16	FRONT STRIKER PLATE <i>?</i>	1	\$ 244.00	
17	FRONT BUMPER LOWER COVER CAP - CENTER / <i>cut</i>	1	\$ 56.00	
18	FRONT RADIATOR BRACKET <i>X</i>	1	\$ 41.00	
19	FRONT RADIATOR COVER <i>X</i>	1	\$ 244.00	
20	FRONT BUMPER CAMERA <i>?</i>	1	\$ 1,141.00	
SUB TOTAL SPARE PARTS		:	\$ 9,333.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 4752 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT BUMPER CAMERA WIRING SET ?	1	\$ 572.00	
22	FRONT PARKING AID SENSOR ?	2	TBC	
23	FRONT PARKING AID SENSOR SEAL RING - MC	4	\$ 9.00	
24	FRONT BUMPER FOAM FILLER PIECE ?	1	\$ 102.00	
25	FRONT BUMPER REINFORCEMENT BAR ?	1	\$ 916.00	
26	FRONT BUMPER GUIDE SUPPORT - LH / RH ?	2	\$ 78.00	
27	FRONT BUMPER TOP COVER ?	1	\$ 123.00	
28	AIR COND STICKER ?	1	\$ 8.00	
29	HORN - LH / RH ?	2	\$ 267.00	
30	HORN BRACKET - LH / RH ?	2	\$ 44.00	
31	FRONT FENDER - LH X R	1	\$ 1,286.00	
32	FRONT FENDER ATTACHEMENT PARTS X	1	\$ 63.00	
33	FRONT FENDER BRACE - LH X	1	\$ 88.00	
34	FRONT FENDER BRACKET - LH X	1	\$ 32.00	
35	FRONT BONNET - DO	1	\$ 3,508.00	
36	FRONT BONNET IMPACT PROTECTION - MC	1	\$ 28.00	
37	FRONT BONNET HINGE - LH / RH ?	2	\$ 146.00	
38	FRONT BONNET ATTACHEMENT PARTS ?	1	\$ 296.00	
39	FRONT BONNET STRIKER - LH / RH ?	2	\$ 220.00	
40	FRONT BONNET INSULATION COVER X	1	\$ 219.00	
SUB TOTAL SPARE PARTS		:	\$ 8,005.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 4752 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT BONNET HINGE COVER - LH / RH <i>X</i>	2	\$ 82.00	
42	FRONT BONNET BOWDEN CABLE <i>?</i>	1	\$ 58.00	
43	FRONT BONNET BOWDEN CABLE COVER <i>?</i>	1	\$ 10.00	
44	FRONT BONNET RELEASE CABLE <i>?</i>	1	\$ 58.00	
45	FRONT BONNET RELEASE LEVER <i>?</i>	1	\$ 14.00	
46	FRONT BONNET LOCK <i>?</i>	2	\$ 427.00	
47	FRONT BONNET GAS ABSORBER <i>X</i>	1	\$ 104.00	
48	FRONT HEADLIGHT MOUNTING - LH / RH <i>?</i>	2	\$ 236.00	
49	FRONT HEADLIGHT - LH <i>✓ CUT (photo)</i>	1	\$ 5,589.00	
50	FRONT HEADLIGHT LIFT CYLINDER - LH <i>?</i>	1	\$ 210.00	
51	FRONT HEADLIGHT HOSE - LH <i>?</i>	1	\$ 80.00	
52	FRONT RADIATOR SUPPORT <i>?</i>	1	\$ 1,272.00	
53	TEMPERATURE SENSOR BRACKET <i>?</i>	1	\$ 7.00	
54	AIR COND CONDENSER <i>?</i>	1	\$ 551.00	
55	ADDITIONAL RADIATOR <i>?</i>	1	\$ 920.00	
56	RADIATOR <i>?</i>	1	\$ 1,035.00	
57	COOLANT <i>?</i>	6	\$ 266.00	
58	FRONT AIR GUIDE - LH / RH <i>?</i>	2	\$ 76.00	
59	FRONT AIR GUIDE - UPPER / LOWER <i>?</i>	2	\$ 82.00	
60	FRONT WHEEL ARCH COVER - LH / RH <i>✓ nrc (photo)</i>	2	\$ 1,072.00	
SUB TOTAL SPARE PARTS		:	\$ 12,149.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 4752 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	AIR COND COMPRESSOR TO AIR CON CONDENSER 1	1	\$ 337.00	
62	AIR COND CONDENSER TO CUT OFF POINT 1	1	\$ 330.00	
63	FRONT NO PLATE BT	S/N	\$ 60.00	
64	SUNDRIES 1		\$ 400.00	
TOTAL SPARE PARTS		:	\$ 30,614.00	
TOTAL LABOUR CHARGES		:	\$ 13,624.00	
GRAND TOTAL		:	\$ 44,238.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Steve (LKK)
11/1/92, 11.30am

OD-M AL
Excl - ?
P/P
My AL My
6 dys

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

<u>LKK Auto Consultants</u> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:	
--	--

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT