

⏪

⏩

1 of 2 ?

⏮

⏭

100% ▾

🖨

🔍 Find | Next



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref: CS3/CTI22000413/Gqf3		
3 ANSON ROAD #16-00		Date: 12/01/2022		
SPRINGLEAF TOWERSINGAPORE 079909		Code: CTI		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	YM 9440P	Veh. Inspected	SLT 8006J	
Policy No.		Coverage (\$)	0.00	
Claim No.	SNM22D200186C02	Excess (\$)	0.00	
Assign From	CHEE SO CHOW	Assign Date	12/01/2022	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	07/01/2022	Inspection Date	12/01/2022	
Survey held at	RUI CHUAN CAR REPAIRING BLK 3006 UBI ROAD 1 #01-340 SINGAPORE 407800			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				